Dave, Route to File

0016

RECEIVED
JUL 17 1995
DIV. OF OIL, GAS & MINING

Consolidation Coal Company
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

Mr. Daron R. Haddock
Permit Supervisor
Division of Oil, Gas, and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1230

12 June 1995

ACT/015/015 #20

RE: Emery Temp. Coal Stockpile Inspection Report

Dear Mr. Haddock:

Enclosed is the 2nd Qtr. Inspection Form of the Temp. Coal Stockpile, where the waste rock is being stored, at the Emery Mine. The form has been certified by a registered P.E. from our St. Louis office.

If you have any questions please call me at (801) 286-2301.

Sincerely,

Stephen R. Behling

Stephen R. Behling
General Mine Foreman
Emery Mine

attachments: Inspection Form certified by a P.E.

RECEIVED
JUL 17 1995
DIV. OF OIL, GAS & MINING

INSPECTION FORM

COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name Stephen R. Behling Title General Mine Foreman

Date 6-26-95 Date last inspected 3-20-95

Site Name Emery Temp. Coal Stockpile Mine Name Emery

Refuse Facility ID # 1211-UT-09-00079-01

Refuse piles---Part A only
Impoundments---Part A and Part B

Part A

1.	Foundation preparation (vegetation, topsoil removal?)	✓ Yes	___ No
2.	Lift Thickness (inches)	___	___
3.	Compaction (4 to 6 complete passes)	___ Yes	✓ No
4.	Burning* (specify extent and location)	___ Yes	✓ No
5.	Angle of Slope (degrees)	N/A	___
6.	Seepage* (specify location, color, & appr. volume	___ Yes	✓ No
7.	Cracks or scarps* (location, size)	___ Yes	✓ No
8.	Major erosion problems* (location and extent)	___ Yes	✓ No
9.	Water impounding against toe*	___ Yes	✓ No

Part B

10.	Embankment freeboard (feet)	___	___
11.	___Increase___Decrease in water level (feet)	___ Yes	___ No
12.	Sumps or sinkholes in slurry surface	___ Yes	___ No
13.	Clogging* (pipes, ditches, spillway)	___ Yes	___ No
14.	Trash racks clear and in place	___ Yes	___ No

* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

Inspection Category	Comments
	No changes in conditions
	No problems evident.

ERVIN ANDERSON
062-0038535
REGISTERED PROFESSIONAL ENGINEER OF ILLINOIS

Ervin Anderson 7-3-95

FORM 1