0018

Pat Incoming

Consolidation Coal Company
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

September 20, 2000

Director Division of Water Quality
Utah Department of Environmental Quality
Division of Water Quality
288 North 1460 West
Post Office Box 144870
Salt Lake City, Utah 84114-4870

RECEIVED
DIVISION OF
OIL, GAS AND MINING

Re: August 2000 Discharge Monitoring Reports for UPDES Permit No. UT0022616

Dear Sir/Madam

I have enclosed a copy of Consolidation Coal Company's Emery Deep Mine UPDES Discharge Monitoring Reports for the reporting period from August 1, 2000 through August 31, 2000.

Mine dewatering pumps for outfalls 001, 003, and 004 only discharged eight days in August due to problems with #3 pump.

Outfall 004 started discharging in June. Point weighted averages are for outfalls 001, 003, and 004.

Outfalls 002, , 005, 006, 007 and 008 did not discharge during the reporting period. Discharge Monitoring Reports for these outfalls are designated as "No Discharge".

If you have any questions or comments, please contact me at your convenience. "I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations".

If you have any questions with regard to this matter, please contact John Gefferth at (618) 625-6850 or Steve Behling at (435) 286-2301.

Sincerely,

Stephen R. Behling

Stephen R Behling
General Mine Foreman

c:\npdes\updesrep.win
Enclosures
cc: Director, Utah Division of Oil, Gas & Mining
John Gefferth
NPDES File