

R5E R6E
T22S
T23S
SEVIER CO
EMERY CO
BUFFER ZONE
(NO PILLARING)
Gravel Pit
Springs
Emery Mine
County Rd #915
County Rd #907
Christiansen Wash
1000 0 1000 FT.
FIRST NORTH INCIDENTAL BOUNDARY CHANGE AREA
PERMIT BOUNDARY
FEDERAL LEASE U-5287
PROPERTY LINE
FEDERAL LEASE U-50044
THIS MAP IS FOR INFORMATIONAL PURPOSES ONLY. COORDINATES ARE NOT TO MINE DATUM.
CONSOLIDATION COAL COMPANY
SESSER ENGINEERING
P.O. BOX 566, SESSER, IL 62884
SURFACE AND COAL OWNERSHIP
MINE EMERY MINE
DATE 10-29-03
REV.
CHKD. PDC
SCALE AS NOTED
APPD. PDC
DRAWING NO.
FILE
DRAWN SWF
SHEET 1 OF 1
PLATE I-1
04/05 ADDED PROPOSED BOUNDARY
10/03 ADD COUNTY ROAD
REV. DATE COMMENTS