0025

File #7 & #10
ACT/015/017
Copy to Mary, Tom M., Pam, Ev, Cy, Dave L.
JIM

MAR 07 1983

RECEIVED
MAR 02 1983
DIVISION OF
OIL, GAS & MINING

EMERY MINING CORPORATION

A SAVAGE BROTHERS COMPANY

February 25, 1983

State of Utah
Natural Resources & Energy
Division of Oil, Gas & Mining
4241 State Office Building
Salt Lake City, UT 84114

ATTENTION: JIM SMITH

Dear Jim:

As required by UMC 817.99 this letter is to inform the Division of a slope failure that occurred on February 15, 1983 at our Church Mine facilities.

A bin type retaining wall supporting a portion of the Little Dove yard area failed allowing material behind it to slide down the slope onto the Deseret yard. Immediate action to protect the safety of workman in the general area was put into effect. Cleanup and stabilization efforts began that day and finished the following day.

Dave Lof of the Division staff was notified the day it happened and visited the site the following day.

If you have further questions please notify me.

Sincerely,

Larry J. Guymon

Larry J. Guymon
Manager of Construction Engineering

LJG/bb

cc: Chris Shingleton
Bill Zeller
Jim Hamlin
Morgan Moon
George Bell

P.O. Box 310 • Huntington, Utah 84528 • (801) 687-9821