
U-47979
U-022918
(KINGSTON)
SL-064607
-064621
SL-066116
SL-070645
U-02292
FEE
U-040151
U-02664
U-1358
SL-064900
U-044025
SL-050133
U-47978
INSUFFICIENT DATA
BLIND CANYON OUTCROP
DEER CREEK FAULT
PLEASANT VALLEY FAULT
STUMP FLAT FAULT
T. 17 S., R. 7 E.
T. 18 S., R. 7 E.
2-9
LEGEND
U.P.&L.CO. PERMIT BOUNDARY LINE
FEDERAL COAL LEASE BOUNDARY LINE
COAL OUTCROP
FAULTS (Ball is on downthrown side with 140' of displacement.)
SECTION CORNER
FOUND SECTION CORNER
EM-26C SURFACE DRILL HOLE (●=Completed, O=Proposed) (EM-26C=East Mtn. Drill Hole No. 26, C=Cored)
IN MINE DRILL HOLE (+=Completed, +=Proposed)
ROADS
EXISTING MINE WORKINGS
U-47978 FEDERAL COAL LEASE NUMBER
DATE
REVISIONS
BY
CHK.
Sheet 3
Sheet 2
SALT LAKE BASE & MERIDIAN
MINE WORKINGS UPDATED TO:
EAST MOUNTAIN PROPERTY
EMERY COUNTY, UTAH
BLIND CANYON
OVERBURDEN ISOPACH MAP
SHOWING THE THICKNESS OF COVER
ABOVE THE BLIND CANYON COAL SEAM
UTAH POWER & LIGHT COMPANY
DEPARTMENT OF MINING & EXPLORATION
DRAWN BY: A.W.ARROW
CHECKED BY:
DATE: 7 NOV 1983
SCALE
SHEET NO.
DRAWING NUMBER
1 of 3
CE-10539-EM