0025

Document Information Form

Mine Number: C/015/017

File Name: Internal

To: DOGM

From:

Person N/A

Company UNITED STATES DEPARTMENT OF THE INTERIOR

Date Sent: MAY 20, 1985

Explanation:

MINE SITE EVALUATION INSPECTION REPORT.

cc:

File in:
C/ 015, 017, **Internal**
Refer to:
- ❑ **Confidential**
- ❑ **Shelf**
- ❑ **Expandable**

Date _____ For additional information

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a (Y Y M M):
1b (Batch):
1c (Report):

2. Name of Permittee: Utah Power+Light Co

3. Street Address: Po Box 899

4. City: Salt Lake City

5. State: UT

6. Zip Code: 84110

7. Area Code: 801

8. Telephone Number: 535-4234

9. MSHA Number: 42-00988-

10. Date of Inspection (Y Y M M D D): 850424

11. State Permit Number: ACT 015 017

12. Name of Mine:

13. County Code: 015

14. State Code: UT

15. Strata:

16. State Area Office: 01

17. OSM Field Office No.: 02

18. OSM Area Office No.:

19. OSM Sample No.:

20. Type of Inspection (Code): CFL

21. Joint Inspection Yes: X No:

22. Inspector's ID No.: 113

23. Status

A	82	Type of Permit
B	A	Mine Status (Code)
C	20	Type of Facility (Code)
D	02580.0	Number of Permitted Acres
E	00020.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A	☐	Steep Slope	E	☐	Anthracite
B	☐	Mountain Top Removal	F	☒	Federal Lands
C	☐	Prime Farmlands	G	☐	Indian Lands
D	☐	Alluvial Valley Floors	H	☐	Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	1	Distance Prohibitions
B	1	Mining Within Permit Boundaries
C	1	Signs and Markers
D	1	Sediment Control Measures
E	1	Design and Certification Requirements—Sediment Control
F	2	Effluent Limits
G	2	Surface Water Monitoring
H	1	Ground Water Monitoring
I	3	Blasting Procedures
J	1	Haul/Access Road D
K	3	Refuse Impoundmen
L		Other: Specify

Standards That Assure Reclamation Quality and Timeliness

M	1	Topsoil Handling
N	1	Backfilling and Grading
O	1	Following Reclamation Schedule
P	1	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	2	Handling of Acid or Toxic Materials
S	3	Highwall Elimination
T	3	Downslope Spoil Disposal
U	2	Post Mining Land Use

of Operations: Temporary

RECEIVED
MAY 20 1985
DIVISION OF OIL GAS & MINING

File in:
- ☐ Confidential
- ☐ Shelf
- ☐ Expandable

Refer to Record No 0025 Date _____
In C/ 015, 017, Internal
For additional information

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a (Y Y M M):
1b (Batch):
1c (Report):

2. Name of Permittee: Utah Power + Light Co
3. Street Address: Po Box 899
4. City: Salt Lake City
5. State: UT
6. Zip Code: 84110
7. Area Code: 801
8. Telephone Number: 535-4234
9. MSHA Number: 42-00988-
10. Date of Inspection (Y Y M M D D): 85 04 24
11. State Permit Number: ACT 015 017
12. Name of Mine:
13. County Code: 015
14. State Code: UT
15. Strata:
16. State Area Office: 01

17. OSM Field Office No.: 02
18. OSM Area Office No.:
19. OSM Sample No.:
20. Type of Inspection (Code): CFL
21. Joint Inspection Yes: X No:
22. Inspector's ID No.: 113

23. Status

A	82	Type of Permit
B	A	Mine Status (Code)
C	20	Type of Facility (Code)
D	02580.0	Number of Permitted Acres
E	00020.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A		Steep Slope	E		Anthracite
B		Mountain Top Removal	F	X	Federal Lands
C		Prime Farmlands	G		Indian Lands
D		Alluvial Valley Floors	H		Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	1	Distance Prohibitions
B	1	Mining Within Permit Boundaries
C	1	Signs and Markers
D	1	Sediment Control Measures
E	1	Design and Certification Requirements—Sediment Control
F	2	Effluent Limits
G	2	Surface Water Monitoring
H	1	Ground Water Monitoring
I	3	Blasting Procedures
J	1	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L		Other: Specify

Standards That Assure Reclamation Quality and Timeliness

M	1	Topsoil Handling
N	1	Backfilling and Grading
O	1	Following Reclamation Schedule
P	1	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	3	Handling of Acid or Toxic Materials
S	3	Highwall Elimination
T	3	Downslope Spoil Disposal
U	3	Post Mining Land Use
V	3	Cessation of Operations: Temporary
W		Other

RECEIVED
MAY 20 1985
DIVISION OF OIL GAS & MINING

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

26. State Permit Number ACT 015 017

27. Date of Inspection (YYMMDD) 850424

28. Yes ☒ No ☐ Do mining and reclamation activities on the site comply with the plans in the permit? If no, provide narrative to support this determination.

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a. 5 Number of Completes — 29b. 10 Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a. 4 Number of Completes — 30b. 8 Number of Partials

31. Has inspection frequency been met?

31a. Yes ☒ No ☐ Completes — 31b. Yes ☒ No ☐ Partials

32. FEDERAL ENFORCEMENT INFORMATION. [Enter violation number. Check appropriate box(es)]

	Ten-Day Notice No.	Notice of Violation No.	Cessation Order No.	Violation Codes
A				Authorizations to Operate
B				Signs and Markers
C				Backfilling and Grading
D				Highwall Elimination
E				Rills and Gullies
F				Improper Fills
G				Topsoil Handling
H				Sediment Ponds
I				Effluent Limits
J				Water Monitoring
K				Buffer Zones
L				Roads
M				Dams
N				Blasting
O				Revegetation
P				Spoil on the Downslope
Q				Mining Without Permit
R				Exceeding Permit Limits
S				Distance Prohibitions
T				Toxic Materials
U				Other Violations

33. Name of Authorized Representative *(print or type)* CHARLES BOTDORF #113

Signature of Authorized Representative — Date 5/4/85

Signature of Reviewing Official — Date 5/16/85

020
015
070
025

Utah Power & Light Co.
P.O. Box 899
Salt Lake City, UT

Mine Des-Bee-Dove 1 of 3

Permit # ACT 015/017

Date: 4/24/85

Inspector C. Bodard OSM

Inspection Type Complete

Others S. Pruitt U DOGM

#1 Outstanding Federal enforcement actions - none
Outstanding State enforcement actions - none

#2 On April 24 1985 a joint inspection was conducted at Des-Bee-Dove Mine, U.P&L with Sandy Pruitt, U DOGM and mine officer Larry Guymon, U.P.&L. Administrative review was conducted at U.P.&L. Offices before proceeding to the mine.

UDOGM Interim Program approval 5/11/78
U.S. Forest Service Special Use Permit 12/11/77
Bonding - Firemans Fund Insurance Company 2/16/80
UT Dept of Health has authorized America Kinfolk waste site for solid waste disposal.
Plans for permanent sediment storage area NW of sed. pond submitted 6/19/84
Haul/access road between Des-Bee-Dove and Wilberg was submitted in Permanent Program Permit to OSM.

Review of NPDES Permit UT 0023591 DMR's for 3rd and 4th Quarter '84 ~~were~~ was made. Non-compliances have not been properly reported to EPA.
On 11/13/84 a controlled discharge was passed for purpose of repairing a leak in the underclay

value of the sediment pond. Certificate of analysis indicate 7071 mg/l TDS non-compliance during a 1.9 acre feet release. RA was not notified. Notice of violation is recommended. Other certificates of analysis were reviewed for the months of February and March 1985. These are bypass discharges for the purpose of pond clean out.

Field survey included review of Beehive, Little Dove, Deseret, Office/Bathhouse/Parking, tipple, and Materials Storage levels. The Beehive level is littered with debris and salvage from a fire zone. Drainage control thru the levels is practiced and effective. Slopes below the Bathhouse/Parking and Materials Storage levels have been stabilized at this time. Vegetative planting has been attempted using Conwels netting (a geotextile) and grassy annuals.

Perimeter markers and mine I.D. sign are displayed.

The haul/access road is maintained, berms are intact with minor exception, all culverts are open and functional. Culvert inlet at Station 131 will require continuing maintenance as Mancos shale above is unstable and slough.

The designed sediment area NW of sediment is stable. Photographed. And surface erosion has minimal rills. Revegetation of this area will be addressed this Spring. The sediment

pond evidences recent clean out activities and should be revegatated in the same time frame as the sed. storage area.

Topsoil / subsoil stockpile that is adjacent to sediment pond is protected, mulched, and a vegetative cover is being established.

#3 Enforcement action - U Dodm NOV 85-2-6-1
#1 of 1 Failure to notify RA of a NPDES non-compliance discharge

#4 MASIER

Codes	Standards
2	F+G See narrative and Enforcement action RA NOV 85-2-6-1 1+1
3	I, K, Q, R, S, T, U, V - not applicable

C Baldwin #113