0002

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/017

Inspection Date 12/18/90

Permittee/Operator Name PACIFICORP ELECTRIC OPERATIONS (PEO)

Business Address 324 SOUTH STATE STREET P.O. BOX 26128

City SALT LAKE State UT. Zip

Mine DES-BEE-DOVE ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

Company Official(s) Debra Oliveto (Close out w/ Guy David)

State Official(s) HENRY SAUER

Time of inspection 12:45 ☐ a.m. ☐ p.m. to 2:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection Weather conditions Light snow accumulation, clear + cold

Acreage ~~[illegible]~~ 2847 ☒ Permitted ~~[illegible]~~ 74.5 ☒ Disturbed ☐ Regraded ☐ Seeded ~~[illegible]~~ 74.5 ☒ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/07

Inspection Date 12/18/90

Please number comments to correspond with topics on previous page.

2) Signs and Markers:
The mine identification sign is legible and in place. Disturbed area markers are clearly visible and properly placed.

4) Hydrologic Balance - Other Sediment Control Measures
The first silt fence encountered on the right side of the Des-Bee-Dove Sediment Pond access road needs to be cleaned prior to spring runoff

Copy of report mailed to John Kathman (O.S.M) Blake Webster (P.E.O.

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Henry Sauer No. 37

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE