0014

UTAH POWER & LIGHT COMPANY

LEGAL OFFICES
SIDNEY G. BAUCOM
SENIOR VICE PRESIDENT AND GENERAL COUNSEL
ROBERT GORDON
535-4258
THOMAS W. FORSGREN
535-4261
VERL R. TOPHAM
535-4259

P. O. BOX 899
SALT LAKE CITY, UTAH 84110

SAM F. CHAMBERLAIN
535-4265
ROSEMARY RICHARDSON
535-4263
RALPH L. JERMAN
535-4253
HELEN J. EDWARDS
535-4255
MARY STIRK
LEGAL ASSISTANT
535-4256
STEVE D. WHITE
CLAIMS SPECIALIST
535-4027

February 27, 1980

Division of Oil, Gas and Mining
1588 West North Temple
Salt Lake City, UT 84116

File

Attn: Mr. K. Michael Thompson
Ms. Denise A. Dragoo

Re: Utah Power & Light Company Deer Creek Mine
ACT/015/018A

Gentlemen:

As I recently informed Mr. Thompson by telephone, the condition referred to in your letter of February 11, 1980, has been corrected. I am advised that the coal has been cleaned out of the Deer Creek channel. I want to point out that the coal was not deliberately pushed into the channel as stated in your letter; rather, it resulted when a workman inadvertently mixed concealed coal with snow during snow removal at the Huntington Plant. It was not until the snow melted that the coal became visible. We have, nonetheless, advised the workmen to take greater precautions to prevent further occurrences in the future.

Very truly yours,

Ralph L. Jerman

RLJ:p

cc: Steve McNeal, Division of Health
Murray Smith, O.S.M., Denver

RECEIVED
FEB 29 1980
DIVISION OF
OIL, GAS & MINING