0010

File

August 5, 1985

TO: Coal File, Inspection and Enforcement Folder

FROM: Sandy Pruitt, Mining Field Specialist SP

RE: Deer Creek Mine, Utah Power and Light, ACT/015/018, Folder #7, Emery County, Utah

The above mentioned mine operation was inspected by Sandy Pruitt, accompanied by Val Payne, on July 18, 1985.

Compliance at the site appeared adequate. The drainage control measures along the conveyor had been maintained since the last inspection. Except the silt fence located near the first junction of the conveyor access road to the mine access road, has a hole in it and should be replaced.

Emery Mining Company was in the process of installing the undisturbed drainage pipe along the existing diversion pipe from the west canyon. This installation was a permit requirment.

A breech at the beginning of the undisturbed drainage diversion bench above the mine yard was repaired by hand during this inspection. Additional, riprap rock was placed in erodible sections of the diversion also.

re

cc: Donna Griffin
Larry Guymon
Joe Helfrich

Note for statistics: See Des-Bee-Dove memo dated August 5, 1985

0292q-24