0005

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gch

inspection report

Permit No. ACT/015/018

Inspection Date NOV. 3, 1987

Permittee/Operator Name UTAH POWER & LIGHT COMPANY

Business Address P.O. BOX 310

City HUNTINGTON State UTAH Zip 84523

Mine DEER CREEK ☐ Surface ☑ Underground ☐ Other

County Emery State UTAH

Company Official(s) RAY CHRISTENSEN

State Official(s) PAMELA grubaugh-LITTIG, HAROLD SANDBECK

Time of inspection 11:30 ☑ a.m. ☐ p.m. to 12:30 ☑ a.m. ☐ p.m. ☑ Partial ☐ Complete

Date of last inspection OCTOBER 16, 1987 Weather conditions RAINY - 40°

Acreage 14,602 ☑ Permitted 26.5 ☑ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☑	☐	☐	☑
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☑	☐	☐	☑
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☑	☐	☐	☑
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☑	☐	☐	☑

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 11/3/87

Please number comments to correspond with topics on previous page.

The mine sequence map was checked and noted where coal is presently being mined. The longwall is in the 9th Right - development in the 10th Right. Generally, the mine site appears to be well-maintained.

4c. Sediment Ponds - The sediment pond is scheduled to be cleaned early next year. No discharge was observed.

6. The waste rock site appears to be at its capacity. The operator noted that an amendment is being prepared for a new waste rock site ~~for Hill~~ Deer Creek. This will hopefully be permitted by March 1988.

16c. The silt fences along the mine access road are operable. They are sturdier than the silt fences they replaced.

18. The new water system is in the process of being installed behind the bathhouse. No problems were noted.

Copy of report mailed to ~~Donna Griffin~~ Brian J Smith, OSM Val Payne, UP&L

Copy of report given to Joe Helfrich, DOGM John Whitehead, DOGM

Inspector's signature Pamela Grubaugh-Littig 11/4/87 No. 20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer