8-17-89 7055

0009

RVS

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/018

Inspection Date August 7, 1989

Permittee/Operator Name Utah Power & Light Mining Division

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Deer Creek ☐ Surface ☒ Underground ☐ Other

County Emery State

Company Official(s) Guy Davis

State Official(s) Bill Malencik & Bill Warmack

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection July 20, 1989 Weather conditions Clear/Warm

Acreage 14620 ☐ Permitted 26.5 ☐ Disturbed ☐ Regraded ☐ Seeded 26.5 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date August 7, 1989

Please number comments to correspond with topics on previous page.

Signs & Markers: Signs & markers were observed on both the new waste rock site and the mine. A question exists on whether or not the main ID signs is located in the proper location. The ID sign is located at the gate adjacent to the sediment pond. The permit boundary is a significant distance below the gate and no sign was observed at the permit boundary. Advised the operator we would advise him if the sign needs to be moved.

Sediment Pond. Waste Rock area contains water, both cells. No evidence of discharge. Mine area, pond is still in the process of being cleaned. Equipment on site, but cleaning operations were delayed as a result of water in the pond. A by-pass culvert has been installed to divert runoff into a temporary sediment pond.

Other Sediment Control. Silt fences, straw bales and berms were checked. This mine has the most extensive coverage of silt fences at both the mine and the waste rock site. One silt fence on the lower end of the conveyor belt line while still functional, should be replaced because of fabric fraying near the top where it is exposed to the sun.

Copy of report mailed to Guy Davis, UP&L
SLC / For: OSM/ Brian Smith; DOGM/ Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature Tom J. Malmnick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

8/7/89

DOGM/IR-2

an equal opportunity employer

11/86 001049