3-27-89
1055

0017

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gh RVS

inspection report

Permit No. ACT/015/018
Inspection Date MARCH 9, 1989

Permittee/Operator Name UTAH POWER & LIGHT MINING DIVISION
Business Address P.O. BOX 310
City HUNTINGTON State UT Zip 84528
Mine DEER CREEK ☐ Surface ☒ Underground ☐ Other
County EMERY State UT
Company Official(s) GUY DAVIS
State Official(s) BILL WAKMACK
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection FEB. 14, 1989 Weather conditions CLEAR & WARM
Acreage 14620 ☒ Permitted 26.5 ☒ Disturbed ☐ Regraded ☐ Seeded 26.5 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 3/9/89

Please number comments to correspond with topics on previous page.

GENERAL: SNOW MELT WAS OCCURING THROUGHOUT THE MINE SITE ESPECIALLY IN THE UPPER CANYON AREAS. RUNOFF WAS PROPERLY CONVEYED THROUGHOUT THE WATER COLLECTION SYSTEM.

2. SIGNS & MARKERS: THE ADDITIONAL PERIMETER MARKERS REQUESTED IN THE PREVIOUS INSPECTION REPORT (2/14/89) HAVE BEEN MARKED & SHOULD BE INSTALLED BY 3/10/89.

3. DIVERSIONS: THE CULVERT INLETS NEAR THE WAREHOUSE & NON-COAL WASTE AREA WERE CLEANED & FUNCTIONING PROPERLY. THE BERM ALONG THE SPRING DIVERSION CHANNEL NEAR THE FAN HAS BEEN COMPLETED.

4d. OTHER SEDIMENT CONTROLS: SILT FENCING WAS BEING INSTALLED ALONG THE ACCESS ROAD & DIKE AT THE NEW WASTE ROCK FACILITY.

Copy of report mailed to Guy Davis (UP&L) FILED TO: PFO

Copy of report given to SLC FOL: Joe Helfrich (DOGM), Brian Smith (OSM)

Inspector's signature William A. Warmack 3/10/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer