0002

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Job page

7055

inspection report

(Utah Power & Light)

Permit No. ACT/015/018
Inspection Date ~~12/18/90~~

Permittee/Operator Name PACIFICORP ELECTRIC OPERATIONS
Business Address ~~[illegible]~~ PO BOX 310
City HUNTINGTON State UTAH Zip 84528
Mine DEER CREEK ☐ Surface ☒ Underground ☐ Other
County EMERY State UTAH
Company Official(s) GUY DAVIS
State Official(s) TOM MUNSON
Time of inspection 8:30 ☒ a.m. ☐ p.m. to 1:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 11/27 - 28 Weather conditions SUNNY
Acreage 14668 ☒ Permitted ☐ Disturbed 56 ☒ Regraded ☐ Seeded 56 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☒	☐	☐	☒
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☒
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 12/18/90

Please number comments to correspond with topics on previous page.

4c. Sediment ponds and impoundments -
Seeding top of dam and ~~side~~ inslope was necessary due to disturbance due to cleaning of pond. Rock moved during this seeding will not be replaced so access to the pond can be maintained for cleaning and surveying. This is O.K. as the rock served no purpose.
4e. Based on the discharge of water from the Deer Creek Mine, the operator has been required to submit water quality data on a daily basis and provide this data for five stations on Deer Creek and Huntington Creek. As the impacts associated with this discharge become more clearly identified and the magnitude more defined the revision of the PHC will be considered an on-going process. ~~On~~ All stream sites were visited. Samples were taken at DCC-1, DCC-5, and HCC-5 for TSS, SS, COND., +OIL+GREASE. This information

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 12/18/90

Please number comments to correspond with topics on previous page.

will be distributed to the appropriate agencies (DEPT. OF HEALTH AND DEPT. OF WILDLIFE RESOURCES) Turbidity samples were taken at a number of sites along Huntington Creek and used as an indicator of potential problems with the stream channel. No areas of undercutting, headcutting or unstability were noted other than increased contributions ~~from~~ of turbidity in the lower stretches of Deer Creek where it cuts across ~~the Mancos Shale which~~ more clayey formations. ~~Through~~ Complete mixing of Huntington Creek and Deer Creek occurs at the confluence. Particles in suspension appear to be carried down Huntington Creek for a significant distance as evidenced by the current sampling program. All procedures carried out by the operator have been considered appropriate. No significant impacts were noted. All water quality data must be received prior to the next discharge!

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 12/18/90

Please number comments to correspond with topics on previous page.

11. The operator has reclaimed and reseeded several areas along the Deer Creek access road with hay mulch and netting. The areas were covered with snow, but looked roughed up and heavy mulched.

Copy of report mailed to Brian Smith (OSM) GUY DAVIS (UP+L) BILL MALENCIK (DOGM)

Copy of report given to JOE HELFRICH (DOGM)

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer