0021

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/018

Inspection Date 4/11/91

Permittee/Operator Name Pacificorp Electric Operations

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Deer Creek ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Guy Davis

State Official(s) Bill Malencik

Time of inspection 8:30 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 3/25 & 26/91 Weather conditions

Acreage 14668 ☐ Permitted 56 ☐ Disturbed ☐ Regraded ☐ Seeded 56 ☐ Bonded

Enforcement Action None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 4/11/91

Please number comments to correspond with topics on previous page.

General Comments. Guy Davis, PEC and the undersigned were accompanied on this inspection by two Energy West Employees.

This partial inspection covered the mine site, belt line, and did not cover the new waste rock site.

In general the mine site was in compliance; however, some items require routine maintenance.

Stream Channel Diversion. Checked the new culvert on Deer Creek. This was the subject of a NOV. The culvert was in place. The disturbed area has not been mulched, but Mr. Davis indicated that the work would be completed to meet the deadline dates.

Diversion. The following diversions are in need of routine maintenance:

- clean drop drains - NE of parking lot
- clean debris - inlet #4
- remove material that had accumulated in the truck load out ditch

Other Sediment Control

- Sed Trap by the tipple needs to be cleaned
- Silt fences adjacent to the beltline needs routine maintenance - refasten top in some places to wire mesh.
- Coal material cleaned from beltline at C-1 & C-2 transfer should be removed and stored at the waste rock site.

Copy of report mailed to PEO/Guy Davis; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PEO

Inspector's signature Wm. J. Grabowski No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

4/12/91

DOGM/IR-2

an equal opportunity employer

11/86 001049