UTAH
NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

0026

inspection report

Permit No. Act/015/018
Inspection Date Jan 15, 1993

Permittee/Operator Name PacifiCorp
Business Address P.O. Box 1005,
City Huntington State Ut Zip 84528
Mine Deer Creek ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Guy Davis
State Official(s) Bill Malencik
Time of inspection 8:30 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 12/29/92 Weather conditions Cloudy/Mine Site Snow Covered
Acreage 14668 ☐ Permitted 56 ☐ Disturbed ☐ Regraded ☐ Seeded 56 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☒
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/018

Inspection Date 1/15/93

Please number comments to correspond with topics on previous page.

General Comments The mine site was covered with twenty-four inches of snow. The operating areas had been cleared of snow. It should be noted that the MRP does not have designated areas for snow storage. It follows that snow from the disturbed area must be treated the same as disturbed runoff from rainfall. The permittee was considering pushing snow off the storage pad to the outslope. It would all drain into the sediment pond. However, they elected to request an amendment to collect, haul and store snow from portions of the mine site to the waste rock site.

Signs & Markers ID signs have been corrected to the title PacifiCorp in lieu of PacifiCorp Electric Operations.

Other Transportation Facilities One cover on the upper beltline was missing. Also the operator had remove snow from the beltline covers in some areas.

Support Facilities The substation was being dismantled at the time of the inspection. The concrete storage devices have been completed and as built drawings are in the process of being repaired

Copy of report mailed to PC / Guy Davis; OSM / Brian Smith; DOGM / Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tom J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

1/19/93