0007

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: X Complete: ___ Exploration: ___
Inspection Date & Time: 10/19/95 12:30 to 3:30
Date of Last Inspection: 8/23/95

Mine Name: Deer Creek County: Emery Permit Number: **ACT/015/018**
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 1005, Huntington, Utah 84528
Type of Mining Activity: Underground X Surface ___ Prep. Plant ___ Other ___
State Officials(s): Susan White and Mele Tuuefiafi
Company Official(s): Karl Houskeeper
Federal Official(s): None
Weather Conditions: Warm and fair
Existing Acreage: Permitted-14,740 Disturbed-93 Regraded-___ Seeded-___ Bonded-93
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: ___Exploration/ X Active/___Inactive/___Temporary Cessation/___Bond Forfeiture
Reclamation (___Phase I/___Phase II/___Final Bond Release/___Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[X]	[ ]	[X]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[X]	[ ]	[X]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[X]	[ ]	[X]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[X]	[ ]	[X]	[ ]
13. REVEGETATION	[X]	[ ]	[X]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	[ ]	[X]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/018

DATE OF INSPECTION: 10/19/95

(Comments are Numbered to Correspond with Topics Listed Above)

Deer Creek Mine Yard

The surface facilities of the main mine site was observed. The mine yard appeared neat and orderly. All observed culverts and drainages were clear and free of obstruction.

Rilda Canyon Surface Facilities

The surface facilities is still under construction. One portal has broken out with the other yet to break out. The pad area is still being built up with Hillficker constructed fill on the outside, adjacent to the stream. The stream was not flowing at this inspection.

The road to the pad is nearly completed, with slopes mostly dressed ready for seeding. A small amount of topsoil remained near the pad area for transport to the main topsoil area. The operator was reminded to keep any construction equipment within the disturbed area boundary.

Copy of this Report:
Mailed to: OSM, Karl Houskeeper (PacifiCorp)
Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White #35 Date: 10/24/95