
STATE
ML-21568
U-68082
SL-062648
U-54762
UTU-77975
JOES VALLEY FAULT
D 1500'
ML-48258
ML-48258
Subleased
I.P.A.-50%
Andalex
Resources
50%
U-78953
U-46484
MILL FORK FAULT GRABEN
R. 6 E.
R. 7 E.
U-024317
U-06039
SL-051221
U-2810
SL-050862
N
I certify that I am a Licensed Professional Geologist in the State of Utah and do also certify that this drawing/plan was prepared by me or under my direction and is accurate as depicted and was compiled using industry accepted methods.
Kenneth S. Fleck 4/19/05
KENNETH S. FLECK NO. 5224883-2250 DATE
LEGEND
PACIFICORP EAST MOUNTAIN PROPERTY BOUNDARY
FEDERAL LEASE BOUNDARY
U-024317 LEASE NUMBERS
FAULT (DASHED WHERE INFERRED)
SANDSTONE CHANNELS
DRILL HOLES
SECTION LINES
SECTION NUMBERS
RECEIVED
JUN 28 2005
DIV. OF OIL, GAS & MINING
CAD FILE NAME/DISK#: HM-2A
HM-2A
ENERGY WEST
MINING COMPANY
HUNTINGTON, UTAH 84528
EAST MOUNTAIN PROPERTY
HIAWATHA COAL SEAM
IN-MINE WATER MONITORING LOCATIONS
DRAWN BY: K. LARSEN
SCALE: 1"=1000'
DATE: APRIL 19, 2005
CE-10908-DR
DRAWING #:
SHEET 1 OF 1
REV.