STATE
ML-21568

U-68082

SL-062648

U-54762

ML-48258
Subleased
I.P.A.-50%
Andalex
Resources
50%

U-78953

U-46484

U-024317

ML-48258

U-06039

U.P.&L. CO.
FEE

UTU-77975

UTU-84285

JOES VALLEY FAULT

PROJECTED MILL FORK CANYON FAULT ZONE

SL-051221

U-2810

R. 6 E.
R. 7 E.

T. 17 S.

N

LEGEND

- LEASE BOUNDARY
- U-024317 LEASE NUMBERS
- FAULT (DASHED WHERE INFERRED)
- SANDSTONE CHANNELS
- EM-182 DRILL HOLES
- SECTION LINES
- 23 SECTION NUMBERS

NVP-4, M-1, M-9, S-220, EM-178, EM-179, EM-211, EM-192, EM-201, EM-205, EM-202, EM-186, HC-4, EM-204, EM-209, HC-3, EM-191, EM-207, EM-210, EM-196, EM-208, CLB-1 (USGS-10), EM-190, EM-212, HC-2, EM-198, EM-176, EM-180, DH-2-76A, B-930, B-928, EM-206, B-916, EM-199, EM-209, B-920, B-929, EM-197, B-915, EM-181, HCD-1, EM-183, EM-189, B-913, EM-169, B-914, B-917, EM-170, B-911, B-912, B-908, B-909, HC-5, MC-4-3, MC-4-4, MC-4-5, MC-4-6, MC-4-7, MC-4-1, DH-2, HCD-2, EM-203, CLB-2 (USGS-2), EM-171, DH-12, MC-4-8, B-901, B-903, B-910, EM-195, EM-182, B-894, B-889, B-888, B-887, EM-175, EM-198, EM-172, HC-1, DH-10, MC-4-2, DH-4, DH-8, DH-6, DH-3, DH-7, DH-9, DH-1, B-896, B-897, B-898, EM-184, EM-194, B-895, B-891, CLB-3A (USGS-3), EM-173, B-892, B-890, B-886, EM-193, B-884, EM-174, B-885, SLB-3 (USGS-9), AB-881, A-882, B-880, B-883, B-879, SLB-1 (USGS-1), EM-153, EM-154, EM-107, EM-185, EM-48, EM-187, EM-52, EM-49, EM-51, EM-105, EM-50, EM-177, UGMS-2, SLB-9 (USGS-8), EM-168, EM-167, EM-166, EM-56, EM-164, EM-163, EM-162, EM-161, EM-160, EM-159, EM-158, EM-55, EM-53, EM-47, EM-157, EM-155, EM-156, SLB-2A (USGS-6), SLB-5 (USGS-5), EM-46

1500' D

25' D

20' D

UD

RECEIVED
APR 13 2010
DIV. OF OIL, GAS & MINING

CAD FILE NAME/DISK#: HM-2B.DWG

HM-2B

ENERGY WEST MINING COMPANY
A SUBSIDIARY OF PACIFICORP

EAST MOUNTAIN PROPERTY
BLIND CANYON COAL SEAM
IN-MINE WATER MONITORING LOCATIONS

DRAWN BY:	K. LARSEN	CE-10909-DR
SCALE:	1"=1000'	DRAWING #:
DATE:	APRIL 6, 2010	SHEET 1 OF 1 REV.

DATE	REVISIONS	BY	CHK
4-6-2010	UPDATED MINE WORKINGS, DRILL HOLES, AND SANDSTONE CHANNELS	KJL	