0002

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Emery Mining Company
Business Address: P.O Box 310, Huntington UTAH 84528
Mine Name: Wilberg Permit Number: ACT/015/019
Type of Mining Activity: Underground x Surface ___ Other ___
County: Emery
Company Official(s): Val Payne
State Official(s): Barton Kale
Inspection Date and Time: 12/12/85 1030-4pm
Partial: ___ Complete: X Date of Last Inspection: 11-27-85
Weather Conditions: Clear - Sunny
Acreage: Permitted 14,896.2 Disturbed 41.00 Regraded ___ Seeded ___ Bonded 41.00
Enforcement Action: Modification of NOV 85-6-14-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS	X			
2. SIGNS AND MARKERS	X			
3. TOPSOIL	X			
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	X			
b. DIVERSION'S	X			
c. SEDIMENT PONDS AND IMPOUNDMENTS	X			
d. OTHER SEDIMENT CONTROL MEASURES	X			
e. SURFACE AND GROUNDWATER MONITORING	X			
f. EFFLUENT LIMITATIONS	X			
5. EXPLOSIVES			X	
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	X			
7. COAL PROCESSING WASTE	X			
8. NONCOAL WASTE	X			
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES			X	
10. SLIDES AND OTHER DAMAGE			X	
11. CONTEMPORANEOUS RECLAMATION			X	
12. BACKFILLING AND GRADING			X	
13. REVEGETATION			X	
14. SUBSIDENCE CONTROL			X	
15. CESSATION OF OPERATIONS			X	
16. ROADS				
a. CONSTRUCTION	X			
b. DRAINAGE CONTROLS		X		
d. SURFACING	X			
e. MAINTENANCE	X			
17. OTHER TRANSPORTATION FACILITIES	X			
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS			X	

INSPECTION REPORT
(Page 2)

Permit Number: ACT/015/019 Date of Inspection: 12-12-85

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

No. B The area below the entrance stop sign the subject of NOV-85-6-14-1 is still out of compliance and therefore not terminated. A significant amount of work was completed but due to the frozen ground the straw bale dams could not function. An extension to Jan 6 1986 was given to allow the operator to re-key in the straw bales in this area.

Copy of this Report:
Mailed to: Donna Griffin, Larry Grymer
Given to: Joe Helfrich

Inspectors Signature and Number: Brian D. Cole #6 1/13/86

0365Q 1-2

Inspection Report
(continuation sheet)

Page____of____

Permit Number:_____

Date of Inspection:_____

COMMENTS

Inspectors Signature, Number and Date:_____

0365Q 3