0014

File

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Utah Power & Light Co.
Business Address: P.O. Box 310 Huntington, UT 84528
Mine Name: Wilberg Permit Number: ACT/015/019
Type of Mining Activity: Underground X Surface ___ Other ___
County: Emery
Company Official(s): Val Payne
State Official(s): Phil Ralphs
Inspection Date and Time: 6/3/86 8:15am - 9:00am
Partial: ✓ Complete: ___ Date of Last Inspection: ___
Weather Conditions: Clear and Warm
Acreage: Permitted ___ Disturbed ___ Regraded ___ Seeded ___ Bonded ___
Enforcement Action: N86-10-1-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS		✓		✓
2. SIGNS AND MARKERS				
3. TOPSOIL				
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS				
d. OTHER SEDIMENT CONTROL MEASURES				
e. SURFACE AND GROUNDWATER MONITORING				
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS				
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS				
d. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

INSPECTION REPORT
(Page 2)

Permit Number: ACT/015/019 Date of Inspection: 6/3/85

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS:

- The purpose of this Inspection was to address the concern mentioned in the Ten-Day-Notice (TDN) # X-86-2-116-3 issued by OSM Reclamation Specialist Henry Austin. The specific concern dealt with the Failure of the Operator to conduct analysis of disposal material in the Wilberg Mine, Waste Rock/Coal Refuse disposal embankment cells prior to covering with excavated material. This inspection was conducted at the UP&L Mining Office in Huntington, Utah. At the time of this inspection the operator was unable to produce the required sampling and analysis data (no sampling of the Disposal Cells has been done). Therefore NOV N86-10-1-1 was issued for "Failure to conduct sampling and analysis as required by the Approved Permit # ACT/015/019. Abatement measures include: 1) Conduct sampling of Disposal Material on completed cells; and, 2) Conduct sampling on future cells, prior to the redistribution of excavated material.

Copy of this Report:
Mailed to: Donna Griffin (OSM) and Val Lagar (UP&L)
Given to: Joe Helfrich and John Whitehead (DOGM)

Inspectors Signature and Number: Philip M Kafalas 6/9/86 #10

0365Q 1-2

Inspection Report
(continuation sheet)

Page____of____

Permit Number:_____

Date of Inspection:_____

COMMENTS

Inspectors Signature, Number and Date:_____

0365Q 3