RE 5-18-87

File

0023

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: UTAH POWER & LIGHT, MINING DIV.
Business Address: P.O. BOX 310, HUNTINGTON, UTAH 84528
Mine Name: WILBERG/COTTONWOOD Permit Number: ACT/015/019
Type of Mining Activity: Underground X Surface ___ Other ___
County: EMERY
Company Official(s): VAL PAYNE
State Official(s): R. SMITH, H. SHEPARD
Inspection Date and Time: 5/13/87; 11:00 – 1:00
Partial: X Complete: ___ Date of Last Inspection: 4/14/87
Weather Conditions: PARTLY CLOUDY AND THUNDERSHOWERS
Acreage: Permitted 11508 Disturbed 425 Regraded ___ Seeded ___ Bonded 425
Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS				
2. SIGNS AND MARKERS				
3. TOPSOIL				
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS				
b. DIVERSION'S				
c. SEDIMENT PONDS AND IMPOUNDMENTS				
d. OTHER SEDIMENT CONTROL MEASURES				
e. SURFACE AND GROUNDWATER MONITORING	X			X
f. EFFLUENT LIMITATIONS				
5. EXPLOSIVES				
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL				
7. COAL PROCESSING WASTE				
8. NONCOAL WASTE				
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES				
10. SLIDES AND OTHER DAMAGE				
11. CONTEMPORANEOUS RECLAMATION				
12. BACKFILLING AND GRADING				
13. REVEGETATION				
14. SUBSIDENCE CONTROL				
15. CESSATION OF OPERATIONS	X			X
16. ROADS				
a. CONSTRUCTION				
b. DRAINAGE CONTROLS				
c. SURFACING				
e. MAINTENANCE				
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS				

INSPECTION REPORT
(Page 2)

Permit Number: ACT/015/019

Date of Inspection: 5/13/87

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

#4d. Inspected berm along road from parking lot to material yard. The berm was functioning properly to prevent road drainage from intermingling with undisturbed drainage.

#14. Inspected subsidence monitoring station NCC, located in Newberry Canyon. Station NCC consisted of a stanchion anchored in bed rock for supporting the distance meter and Theodolite. Eagle nests 61C and 61B and monitoring prisms 1, 3 and 4 were observed through a spotting scope. All subsidence monitoring equipment in Newberry Canyon are functioning properly and conform with the approved MRP.

Copy of this Report:
Mailed to: D. Griffin (OSM), V. Payne (UP&L)
Given to: J. Helfrich, ~~J. Whitehead~~

Inspectors Signature and Number: Richard V. Smith 5/18/87

0365Q 1-2