0019

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/019

Inspection Date JUNE 15, 1988

Permittee/Operator Name UTAH POWER & LIGHT Co.

Business Address P.O. BOX 310

City HUNTINGTON State UTAH Zip 84528

Mine WILBERG/COTTONWOOD ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) VAL PAYNE

State Official(s) PAMELA GRUBAUGH-LITTIG, RICHARD SMITH

Time of inspection 8:00 ☑ a.m. ☐ p.m. to 4:00 ☐ a.m. ☑ p.m. ☐ Partial ☑ Complete

Date of last inspection MAY 19, 1988 Weather conditions

Acreage 11,508 ☑ Permitted 42.5 ☑ Disturbed ☐ Regraded ☐ Seeded 42.5 ☑ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	☐	☐	☑
3. Topsoil	☑	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☑	☐	☐	☐
b Diversions	☑	☐	☐	☐
c Sediment ponds and impoundments	☑	☐	☐	☑
d Other sediment control measures	☑	☐	☐	☑
e Surface and groundwater monitoring	☑	☐	☐	☐
f Effluent limitations	☑	☐	☐	☑
5. Explosives	☑	☐	☐	☐
6. Development waste and spoil disposal	☑	☐	☐	☑
7. Coal processing waste	☐	☑	☑	☐
8. Noncoal waste	☑	☐	☐	☑
9. Protection of fish, wildlife, and related environmental values	☑	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☑	☐	☐	☑
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☑	☐	☐	☑
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☑	☐	☐	☑
c Surfacing	☑	☐	☐	☐
d Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/014

Inspection Date JUNE 15, 1988

Please number comments to correspond with topics on previous page.

1. The new UPDES permit was issued; expires 9-30-92. This permit allows for a 1 TON/day limit for TDS.
- The mining and reclamation permit was issued 7/6/84, this permit will need to be renewed by 7/6/89.
- Blasting records are maintained; no blasts recorded during this quarter.
- SPCC certified 4/8/87. (Spill Prevention and Control Plan)
- Liability insurance is expired (as of 5/1/88). According to the procedure outlined by Division management (memo to file 7-7-87), UP&L has been notified (as of this inspection) that a current certificate of insurance must be on file by the next regular inspection.
- The areas of current mining are: development in 11th West, 3rd South, and 8th East; retreating in the 10th West Panel. Wilberg is working 5 days for 3 shifts.

2. Signs and markers were clearly distinguishable and well maintained.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date June 15, 1988

Please number comments to correspond with topics on previous page.

4c. The flow meter will be properly installed and operable by August 1, 1988 for the old pond at Wilberg mine site.

4d. The sed ponds by the Cottonwood fan portal are operable. The inlet to the upper sed ponds needs some maintenance work done. Will be done by 8-1-88.

4d. Silt fences by the upper fan need maintenance work will be completed by 8-1-88.

The silt fence below the guard shack (mentioned in the 5/19/88 inspection report) was still in need of cleaning during the first part of the inspection. By the end of the inspection, the silt fence was operable. The silt had been removed.

4f. UPDES discharge reports were at the site. Monitoring point 003 was sampled 5/16/88 @ 2.85 gpm.

6. Cells 7/8 are currently being used to store the development waste at the Wilberg Waste Rock site.

8. Used oil is removed from the mine site by Pierce Oil in Price (licensed 2/6/87 by DOGM).

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date June 15, 1988

Please number comments to correspond with topics on previous page.

10b. The drainage from the upper pad to the lower parking lot needs some work. It is currently operable but needs upgrading. This upgrade will be done by 8/1/88.

11. The reclamation by the upper fan is ~~being~~ growing well. Grasses and forbs were noted.

14. Miller Canyon was inspected for signs of spalling or slides that could be related to subsidence. No signs of movement. A "Cottonwood Mine Study Plan" is being proposed as a geotechnical study of subsidence of the UP&L mine areas. This study would be a joint agreement among the FS, BLM, DOGM & UP&L. (First meeting will be held in Price 6/27/88).

Copy of report mailed to PFO, Brian Smith (OSM), and Val Payne (UP&L)

Copy of report given to Joe Helfrich, DOGM

Inspector's signature [signature] No. 20 (6/16/88)

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE