0022

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/019

Inspection Date MAY 19, 1988

Permittee/Operator Name UTAH POWER AND LIGHT

Business Address P.O. BOX 310

City HUNTINGTON State UTAH Zip 84528

Mine WILBERG/COTTONWOOD ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) VAL PAYNE

State Official(s) TOM MUNSON

Time of inspection 12:00 ☐ a.m. ☑ p.m. to 1:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection APRIL 7, 1988 Weather conditions SUNNY

Acreage 11 508 ☑ Permitted 42.5 ☑ Disturbed ☐ Regraded ☐ Seeded 42.5 ☑ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☑
— Other sediment control measures	☑	☐	☐	☑
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☑	☐	☐	☑
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date MAY 19, 1988

Please number comments to correspond with topics on previous page.

4) Sediment ponds and impoundments - The pond was checked for the Oil and Grease problem noted on previous NPDES reports. No evidence of Oily discharge was noted and the stream channel below the discharge pipe did not show any evidence of Oily stains. The flow meter was to be installed shortly and should be checked during the next inspection for proper installation.

4) Other Sediment Control Measures - The R.F. of Grimes Wash inlet area below the waterfalls still exhibited use of concrete equipment in close proximity to the inlet. Straw bales and silt fences in the area need maintenance and will be replaced next week by the operator. Silt fence below the guard shack was full and the operator was requested to use hand work immediately to prevent any

Copy of report mailed to

Copy of report given to

Inspector's signature Tom Munson 5/19/88 No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date MAY 19, 1988

Please number comments to correspond with topics on previous page.

discharge of sediments or coal fines to the stream channel. By the 24th of May the operator is to have cleaned and maintained this sediment control structure. This must be checked on the next inspection for maintenance.

16 Roads - Drainage controls adjacent to the roads were properly maintained and looked in good working order.

Copy of report mailed to PFO, Brian Smith (OSM), Val Payne (UP&L)

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Tom Munson 5/19/88 No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer