0028

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

File

inspection report

Permit No. ACT/015/019

Inspection Date 2/9/88

Permittee/Operator Name UTAH POWER + LIGHT, MINING DIVISION

Business Address P.O. BOX 310

City HUNTINGTON State UTAH Zip 84528

Mine WILBERG/COTTONWOOD ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) CHUCK SEMBORSKI

State Official(s) TOM MUNSON

Time of inspection 9:30 ☒ a.m. ☐ p.m. to 10:30 ☒ a.m. ☐ p.m. ☑ Partial ☐ Complete

Date of last inspection JAN 20, 1988 Weather conditions CLEAR

Acreage 11508 ☒ Permitted 42.5 ☒ Disturbed ☐ Regraded ☐ Seeded 42.5 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 2/9/88

Please number comments to correspond with topics on previous page.

4) SEDIMENT PONDS AND IMPOUNDMENTS:
The NPDES permit for the Wilberg Mine Sediment Pond outfalls 002 and 003 has been changed to reflect a ton/day Total Dissolved Solids limit. The Operator is installing a Electro-Magnetic Flow Meter to accurately determine flow through the decant pipe and compliance with the new limitation. They have been over their limit on Oil and Grease for several samplings. The operator is committed to solving this problem by increasing the length of his decant tube. The next surface inspection should include a survey of possible Oil and Grease contaminants. The operator is working with State Health and has informed them of the problem on January 4, 1988.

4) Surface and Groundwater Monitoring:
The operator has well organized and complete documentation of all sampling. No problems were found. The operator needs to complete baseline sampling on In-Mine site #2.

Copy of report mailed to Brian Smith, OSM, Val Payne, UP&L, Chuck Semborski, UP&L

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Thomas Munson 2-12-88 No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer