0002

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gl

pgl

inspection report

Permit No. ACT/015/019

Inspection Date 10/31/90

Permittee/Operator Name PacifiCorp Electric Operations (UP&L)

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Cottonwood/Wilberg ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Guy Davis

State Official(s) Bruce Malencik

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 10:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 10/18/90 Weather conditions Clear/Cool

Acreage 11532 ☐ Permitted 66 ☐ Disturbed ☐ Regraded ☐ Seeded 66 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☐	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date 10/31/90

Please number comments to correspond with topics on previous page.

General Comments This partial inspection covered the Grimes Wash area, but did not include the Cottonwood Fan area.

Signs & Markers. All required signs and markers are in place. Permittee mentioned when the title change is made they will be replacing all the ID signs

Diversion. Culvert noted in the last inspection report had been cleaned. All culverts and ditches in the tipple area were in good shape

Sediment Pond. Both the north and the south ponds contained water, were not discharging, and were stable.

Sediment Control Measures. Straw bales on the reclaimed access road to the Deer Creek portals were checked. All were fully functional.

Support Facilities. A 100 gallon fuel tank owned by a contractor who is working on site has been installed near the former Cottonwood Fan. The tank, located on a pipe stand was protected by a berm that was of sufficient size that it would contain the fuel within the berm.

Copy of report mailed to PCEO/GUY DAVIS; OSM/BRAIN SMITH; DOGM/JOE HELFRICH

Copy of report ~~given to~~ PFO

Inspector's signature [signature] No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

11/5/90

DOGM/IR-2

an equal opportunity employer

11/86 001049