0020

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/019
Inspection Date 4/11/90

Permittee/Operator Name UTAH POWER AND LIGHT
Business Address PO BOX 10
City HUNTINGTON State UTAH Zip 84528
Mine COTTONWOOD/WILBERG ☐ Surface ☒ Underground ☐ Other
County EMERY State UTAH
Company Official(s) GUY DAVIS
State Official(s) TOM MUNSON
Time of inspection 11:00 ☐ a.m. ☐ p.m. to 12:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 6/12/90 Weather conditions SUNNY
Acreage 1532 ☒ Permitted 66 ☒ Disturbed ☐ Regraded ☐ Seeded 66 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
d — Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 7/11/90

Please number comments to correspond with topics on previous page.

1) Permits

The Spill prevention control plan has been completed and signed by company officials and was viewed in the company's office. A berm was placed around the substation as part of the plan

7) The Waste Rock site was inspected and the following items noted.

1) silt fence in place around topsoil pile
2) silt fence in place around subsoil pile
3) dam was in process of being constructed in 8" lifts, 2 compaction tests/lift.

No new subsoil had been removed or stored due to concerns regarding

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 7/11/90

Please number comments to correspond with topics on previous page.

quality of material and a request to the BLM to reduce subsoil depth from 24 inches to 18 inches would reduce volume of subsoil needed. This action is still pending a decision from BLM.

4d The design of silt fence installation was critiqued with the operator requesting a better attempt to secure the silt fence to additional support, whether it be wire mesh backing or more posts. He was told that wire mesh is the preferred method and will most likely prevent future maintenance.

Copy of report mailed to Brian Smith (OSM), Bill Malencik (DOGM), GUY DAVIS (UP&L)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Tom Munson No. 25

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer