7655 0042 15/19

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/019
Inspection Date Jan 4, 1990

Permittee/Operator Name UP&L
Business Address P.O. Box 310
City Huntington State Ut Zip 84528
Mine Cottonwood/Wilberg ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Val Payne
State Official(s) Bill Malencik
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 12/18/89 Weather conditions Clear/Cold
Acreage 11508 ☐ Permitted 42 ☐ Disturbed ☐ Regraded ☐ Seeded 42 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☒
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 1/4/90

Please number comments to correspond with topics on previous page.

Signs & Markers The I.D signing on the mine site, waste rock and other areas was discussed with the operator. He mentioned that the former two signs have been moved several times based on inspector interpretation of the current regulations. Also, OSM oversight inspections resulted in moving signs. It was concluded that no additional signs are required and/or should be removed until additional clarification is secured.

Other Sediment Control The sediment basin on the upper pad that does not report to a sediment pond, approved plan by the division, is currently under construction. The stand pipe and the downspout has been installed (18"). The height of the berm will be increased and a dewatering device will be installed.

Silt fences were checked and no problems noted. Silt fence on the road side of the leach field had recently been installed. Also new markers were observed.

Development Waste & Spoil Disposal UP&L employees were performing erosion control and drainage work of a maintenance nature on the lower waste rock cell.

Copy of report mailed to UP&L - Guy Davis
SLC - OSM/ Brian Smith, DOGM/ Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tim J. Drakulich No. 26

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

1/5/90.

DOGM/IR-2

an equal opportunity employer

11/86 001049