0018

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/019

Inspection Date April 3 & 4, 1991

Permittee/Operator Name Pacific Corp. Electric Operations

Business Address Box 310

City Huntington State Ut Zip 84528

Mine Cottonwood/Wilberg ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Guy Davis, harvey Lafrenz

State Official(s) Bill Malencik

Time of inspection 4/3/ 8 a.m. ☐ a.m. ☐ p.m. to 4/4/ 2 p.m. :30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 3 Weather conditions Clear/Pleasant

Acreage 11532 ☐ Permitted 101 74 ☐ Disturbed ☐ Regraded ☐ Seeded 101 74 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☒
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 4/3-4/91

Please number comments to correspond with topics on previous page.

Records

Permit - Expires 7/7/94 and transfers between UP&L and Pacificorp have been completed

Stipulations - One stipulation has not been completed, the subject of NOV-91 26-1-1 with an abatement date of 4/15/91.

Surety Bond on file for $2,008,681.00

Liability Insurance recently extended and covers period 2/24/91 to 2/24/92

Waste Rock, Water Monitoring & Sediment Pond Records for the first quarter of 1991 had not been finalized. The permittee stated that all the field work had been completed and the appropriate records are in the process of being prepared. This should be completed in 10 days according to Mr. Davis.

Road Questionnaire: The permittee is gathering information to respond to a questionnaire on the State Highway between the coal mine and the power plant.

Field

Areas covered in the field included the mine site upper, middle & lower pads; waste rock/area below the mine; and the Cottonwood Fan area.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 4/3-4/91

Please number comments to correspond with topics on previous page.

Topsoil. Operator stated all the work had been completed on the waste rock topsoil/subsoil project. Further that the required information would be submitted to the Division on or before 4/15/91.

Sediment Ponds. The sediment pond has been cleaned since the last inspection by the undersigned. The sediment material was transported and placed at the new waste rock site. The upper pond contained runoff and was stable.

Other Sediment Control. The two approved sediment traps have not been constructed. Mr. Davis discussed the project with Harry Lafrenz who would be in charge of the construction. Sediment control measures throughout the property were checked and no problems noted.

Contemporaneous Reclamation. The permittee provided additional information on the this matter including a letter from OSM's Denver Office (Cottonwood Tax Area).

Road Drainage. The NOV below the guard bldg. (former) was checked. No abatement work had yet been undertaken. Mr. Davis discussed on site the matter with Jim Energy West employees in order to come up with the best long term solution to the problem.

Copy of report mailed to Pacificorp/Guy Davis; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tom J. Malencik No. 26

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

4/5/91

DOGM/IR-2

an equal opportunity employer

11/86 001049