0007

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jck pgl

inspection report

Permit No. Act/015/019

Inspection Date Sept 3, 1992

Permittee/Operator Name PacifiCorp Electric Operations

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Cottonwood/Wilberg ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Karl Houskeeper

State Official(s) Bill Malencik

Time of inspection 8:00 ☐ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 8/20-21/92 Weather conditions Pt. Cloudy/Temp 70°/Dry Mine Site

Acreage 11532 ☐ Permitted 102 ☐ Disturbed ☐ Regraded ☐ Seeded 102 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/019

Inspection Date 9/3/92

Please number comments to correspond with topics on previous page.

General Comments. This partial inspection covered the main mine site & waste rock site, not the disturbed area adjacent to Cottonwood Creek, and inactive mine site.

Followup On Prior Inspection. The operator performed environmental preventative measures as suggested in the last inspection. The work consisted of the following:

(1) Waste Rock

- repaired minor rills on the subsoil pile and took steps to control runoff from the top of the pile
- repaired road berm adjacent to the sediment storage area

(2) Main Mine Site

- increased the height of the berm near the transfer station.
- cleaned drop drain/sediment storage in the shop area

Diversions. Drop drain adjacent to the rock dust silo had a potential problem. Some air ducts were stored over part of the down drain. No evidence that water had builtup or short circuited. The operator corrected this problem before the inspection.

Copy of report mailed to PEO/Karl Houskeeper; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature Wm. J. Malenich No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

9/4/92

DOGM/IR-2

an equal opportunity employer

11/86 001049