STATE OF UTAH
NATURAL RESOURCES
Division of Oil, Gas & Mining
3 Triad Center · Suite 350 · Salt Lake City, UT 84180-1203 · (801) 538-5340

ACT/015/019

0001

inspection report

☑ Partial
☐ Complete
☐ Exploration

Inspection Date: December 7, 1995
Time: 8 : 00 ☐am ☐pm to 1 : 00 ☐am ☑pm
Date of Last Inspection: Nov 22, 1995

Mine Name: Cottonwood/Wilberg County: Emery Permit Number: Act 015/019
Permittee and/or Operator's Name: PacifiCorp/Energy West
Business Address: P.O. Box 1005, Huntington, UT 84528
Type of Mining Activity: ☑ Underground ☐ Surface ☐ Prep. Plant ☐ Other
State Officials(s): Bill Malencik
Company Official(s): Karl Houskeeper
Federal Official(s): N/A
Weather Conditions: Clear / Temp 40°s
Existing Acreage: Permitted-11532 Disturbed-102 Regraded-____ Seeded-____ Bonded-102
Increased/Decreased: Permitted-____ Disturbed-____ Regraded-____ Seeded-____ Bonded-____
Status: ☐ Exploration / ☑ Active / ☐ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture
☐ Reclamation (☐ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	☑	☐	☑	☐
2. SIGNS AND MARKERS	☑	☐	☐	☐
3. TOPSOIL	☐	☐	☐	☐
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	☑	☐	☐	☐
b. SEDIMENT PONDS AND IMPOUNDMENTS	☑	☐	☑	☐
c. OTHER SEDIMENT CONTROL MEASURES	☑	☐	☐	☐
d. WATER MONITORING	☐	☐	☐	☐
e. EFFLUENT LIMITATIONS	☐	☐	☐	☐
5. EXPLOSIVES	☐	☐	☐	☐
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	☐	☐	☐	☐
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	☑	☐	☑	☐
8. NONCOAL WASTE	☐	☐	☐	☐
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	☐	☐	☐	☐
10. SLIDES AND OTHER DAMAGE	☐	☐	☐	☐
11. CONTEMPORANEOUS RECLAMATION	☐	☐	☐	☐
12. BACKFILLING AND GRADING	☐	☐	☐	☐
13. REVEGETATION	☐	☐	☐	☐
14. SUBSIDENCE CONTROL	☐	☐	☐	☐
15. CESSATION OF OPERATIONS	☐	☐	☐	☐
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	☑	☐	☑	☐
b. DRAINAGE CONTROLS	☐	☐	☐	☐
17. OTHER TRANSPORTATION FACILITIES	☐	☐	☐	☐
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	☑	☐	☑	☐
19. AVS CHECK (4th Quarter-April, May, June)____(date)	☐	☐	☐	☐
20. AIR QUALITY PERMIT	☐	☐	☐	☐
21. BONDING & INSURANCE	☐	☐	☐	☐

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 015/019

Inspection Date 12/7/95

Please number comments to correspond with topics on previous page.

General Comments This partial inspection covered the mine site, waste rock site, and the Cottonwood new portal area. The bulk of the field time was devoted to the new portal area.

Permit Observed the area in the Cottonwood permit where the operator proposes temporary parking. Took photos of the proposed parking area to maintain a record of the area before parking commences. The amendment is currently in the discussion and analysis stage.

Diversions Observed diversions at the three locations mentioned above and all appeared to be in compliance. With the scarcity of moisture, rainfall and snow the only runoff observed was dust operations.

Sediment Ponds The mine ponds and waste rock pond contained runoff. The two ponds at the Cottonwood new portal area were dry.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 015/019

Inspection Date 12/7/95

Please number comments to correspond with topics on previous page.

Refuse Pile Observed the active refuse pile. Another lift has been started with storage concentrated in the southeasterly portion of the pile. Non-coal waste material had been removed as evidenced by a pile of material stored on the pad. No evidence of impounding was observed, except when sediment liquid cleanout material is temporarily stored.

Roads Roads at the Cottonwood Mine were in good shape. Traffic at the mine is now substantially reduced now that the workers are reporting to the Trail Mtn Mine. Only the coal hauling truck traffic remains at about the same level as before.

Surface Facilities Work had started on the sewer grey water pumping building that will interties parts of the Cottonwood/Trail Mtn sewer systems together. This is covered by an approved DOGM amendment to the respective permits.

Copy of report mailed to PC/Karl Houskeeper, OSM/Marvin Pettie; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PD

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE OPERATOR GOLDENROD – NOV FILE

12/19/95