0001

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gh gh

inspection report

Permit No. ACT/015/025

Inspection Date January 28, 1988

Permittee/Operator Name Co-Op Mining Company

Business Address P.O. Box 1245

City Huntington State UT Zip 84528

Mine Bear Canyon ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) Gerald Hansen

State Official(s) Harold G. Sandbeck, John Whitehead and Daron Haddock

Time of inspection 12:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection December 16, 1987 Weather conditions Clear/Cool

Acreage 900 ☒ Permitted 10 ☒ Disturbed ☐ Regraded ☐ Seeded 10 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☒	☐	☐	☒
b – Diversions	☒	☐	☐	☒
c – Sediment ponds and impoundments	☒	☐	☐	☐
d – Other sediment control measures	☐	☐	☐	☐
e – Surface and groundwater monitoring	☐	☐	☐	☐
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☒	☐	☐	☒
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/025

Inspection Date January 28, 1988

Please number comments to correspond with topics on previous page.

General Comments: Gerald Hansen (Co-Op Environmental Representative) accompanied the undersigned inspector on this partial inspection. The mine site was covered with over two feet of snow. All disturbed area runoff was seen flowing into the sediment pond. No environmental problems were noted.

4.a.) Stream Channel Diversions: The Bear Creek stream was flowing. The stream was inspected and no problems were found. Water monitoring stations BC-1 and BC-2 are located on Bear Creek Stream.

4.b.) Diversions: The majority of the mine site ditches were frozen and covered with snow. The operator intends to periodically clean the ditches before and during the peak runoff season

16.b.) Road Drainage Controls: The undersigned inspector was not able to see a silt fence at a diversion outlet on the access road which leads up to the upper pads. The exact location is the 'E-E' cross section symbol on the Surface Facilities Map, Plate 2-2 which was

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/025

Inspection Date January 28, 1988

Please number comments to correspond with topics on previous page.

revised on 12/06/87. This ditch was frozen with over 3 feet of snow cover. Bear Creek stream was inspected and no signs of pollutants were found. The operator was informed that if a silt fence cannot be found, that one must be installed.

Copy of report mailed to Gerald Hansen, Co-Op and Brian Smith, OSM

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Harold D. Hansen February 3, 1988 No. 27

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE