

NOTE: THE BONDED AREAS INCLUDE ALL AREAS THAT HAVE BEEN DISTURBED AND ARE LOCATED WITHIN THE DISTURBED AND PERMIT AREA AS SHOWN ON THE MAP.

GENWAL COAL COMPANY
P.O. BOX 1201 HUNTINGTON, UTAH
CRANDALL CANYON MINE
SURFACE FACILITIES
SCALE 1"=40' DECEMBER 1, 1986
SURVEYED BY BRUCE WARE
PLATE 3-1 8/8/88