

SCALE: 1" = 400'

DATE: February 15, 2001

ACAD REFERENCE: *2000 SUMMARY*

I hereby certify that the design and/or map contained herein was prepared by me or under my supervision and is true and correct to the best of my knowledge.

Crandall Canyon Project
Hiawatha Seam
2000 Production Areas

LEGEND

Longwall Gob Areas		Jun. 2000 Production Area	
Jan. 2000 Production Area		Jul. 2000 Production Area	
Feb. 2000 Production Area		Aug. 2000 Production Area	
Mar. 2000 Production Area		Sep. 2000 Production Area	
Apr. 2000 Production Area		Oct. 2000 Production Area	
May 2000 Production Area		Nov. 2000 Production Area	
		Dec. 2000 Production Area	

GENWAL RESOURCES, INC.
P.O. Box 1420
195 North 100 West Huntington, Utah 84528
Telephone: (435) 687-9813 Fax: (435) 687-9784

RECEIVED
APR 05 2001
DIVISION OF
OIL, GAS AND MINING

TRESPASS AREA SUMMARY

1. This area of the Panel 6 Blunders was mined during November 1996 and January 1997 according to the revised R2P2 map dated December 1996. The Panel 6 area was mined out and sealed in June 1997.

2. In mid-1998 Genwal Resources Inc. retained the services of a Registered Land Surveyor to investigate BLM concerns that the location of the east property line in Section 1 had been improperly located on the approved October 1996 R2P2 map.

3. On September 22, 1998 the Registered Land Surveyor determined that the location of the eastern property line in Section 1 had been incorrectly located and certified the proper property line as shown, which resulted in an important trespass situation.

4. A trespass assessment was settled with the BLM on December 4, 1999. Genwal Resources Inc. paid the assessment on December 16, 1999. The Department of Oil, Gas and Mining issued a Cessation Order (CO-99-Pt-1) on December 14, 1999, to which Genwal Resources Inc. immediately complied.