0013

C/015/032 Incoming

General Offices: P.O. Box 995 Price, UT. 84501 (435)637-8855
Laboratory: 65 North 300 East Price, UT. 84501

HORIZON LABORATORIES

Report Date
1/31/2008

Client
UtahAmerican Energy Inc.
Genwal Resources, Inc.
PO Box 1077
Price, UT. 84501
Dave Shaver
(435)888-4017

Sample I.D.
002
Sampled By: KDK
Date: 1/28/2008 **Time:** 14:05
Received Date: 1/28/2008 **Time:** 15:40

Field Measurements

Cond. uS	Temp. C	pH	D.O. ppm	Turbidity NTU
1507	7.0	7.9	9.3	

Notes:

Lab I.D. #: 546 Mine Code 08 Site Code 40

Certificate of Analysis

Analyte	Results	Units	MRL	Method	Date	Time	Analyst
Wet Chem.							
Oil & Grease	<5	mg/L	5	EPA 413.1	1/29/2008	9:23	SB
Solids, Total Dissolved	1108	mg/L	20	EPA 160.1	1/29/2008	10:42	SB
Solids, Total Suspended	12	mg/L	4	EPA 160.2	1/29/2008	10:42	SB
Metals by ICP							
Aluminum, Dissolved	0.06	mg/L	0.01	EPA 200.7	1/29/2008	13:06	SB
Aluminum, Total	0.32	mg/L	0.01	EPA 200.7	1/31/2008	13:44	SB
Boron, Dissolved	0.19	mg/L	0.05	EPA 200.7	1/29/2008	13:06	SB
Boron, Total	0.19	mg/L	0.05	EPA 200.7	1/30/2008	16:10	SB
Iron, Dissolved	0.034	mg/L	0.010	EPA 200.7	1/29/2008	13:06	SB
Iron, Total	1.491	mg/L	0.010	EPA 200.7	1/30/2008	16:10	SB
Manganese, Dissolved	0.121	mg/L	0.001	EPA 200.7	1/29/2008	13:06	SB
Manganese, Total	0.122	mg/L	0.001	EPA 200.7	1/30/2008	16:10	SB
Nickel, Dissolved	0.155	mg/L	0.002	EPA 200.7	1/29/2008	13:06	SB
Nickel, Total	0.156	mg/L	0.002	EPA 200.7	1/30/2008	16:10	SB
Selenium, Dissolved	<0.01	mg/L	0.01	EPA 200.7	1/29/2008	13:06	SB
Selenium, Total	<0.01	mg/L	0.01	EPA 200.7	1/30/2008	16:10	SB
Zinc, Dissolved	0.282	mg/L	0.005	EPA 200.7	1/29/2008	13:06	SB
Zinc, Total	0.302	mg/L	0.005	EPA 200.7	1/30/2008	16:10	SB

Brandon Pierce
Technical Director

All reported results meet the requirements of NELAC, except for Balance and Hardness.
Balance and Hardness are calculated from certified results.