0011

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

PERMIT NO.: ACT/041/002 Inspection Date: July 17, 1991
Permittee and/or Operators Name: Southern Utah Fuel Co.
Business Address: P.O. Box P
City: Salina State: Utah Zip: 84654
Mine Name: Convulsion Canyon
County: Sevier State: Utah
Type of Mining Activity: Underground XX Surface ____ Other ____
Company Official (s): Mike Davis
State Officials (s): Stephen J. Demczak
Time of Inspection: 9:00 (X) a.m.( ) p.m. to 12:30 ( )a.m. (X)p.m.
Partial XX Complete: ____ Date of Last Inspection: June 19, 1991
Weather Conditions: Warm 80's
Acreage: Permitted 18301 Disturbed 26.2 Regraded .5 Seeded .5
Bonded 67.8 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

		YES	NO	N/A	COMMENTS
1.	PERMITS	(X)	( )	( )	(X)
2.	SIGNS AND MARKERS	( )	( )	( )	( )
3.	TOPSOIL	( )	( )	( )	( )
4.	HYDROLOGIC BALANCE:				
	a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
	b. DIVERSIONS	(X)	( )	( )	( )
	c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
	d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
	e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
	f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5.	EXPLOSIVES	( )	( )	( )	( )
6.	DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7.	COAL PROCESSING WASTE	(X)	( )	( )	( )
8.	NONCOAL WASTE	(X)	( )	( )	( )
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10.	SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11.	CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12.	BACKFILLING AND GRADING	( )	( )	( )	( )
13.	REVEGETATION	( )	( )	( )	( )
14.	SUBSIDENCE CONTROL	( )	( )	( )	( )
15.	CESSATION OF OPERATIONS	( )	( )	( )	( )
16.	ROADS				
	a. CONSTRUCTION	( )	( )	( )	( )
	b. DRAINAGE CONTROLS	( )	( )	( )	( )
	c. SURFACING	( )	( )	( )	( )
	d. MAINTENANCE	( )	( )	( )	( )
17.	OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18.	SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	( )	( )

an equal opportunity employer

INSPECTION REPORT COMMENTS
(continuation sheet)

PERMIT NO. ACT/041/002 INSPECTION DATE July 17, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit - The surface facilities map was reviewed out in the field. The map was up-to-date but requires additional detail in labeling. The operator will submit a new surface facility map within 30 days of this inspection.

4c. Sediment ponds and impoundments - The sediment pond below mine facility (002) was being cleaned out at the time of the inspection. During the inspection, none of the ponds were discharging.

An AVS check was made with no changes occurring.

Copy of report:

Mailed to: Southern Utah Fuel Co.
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39
Date: 7/22/91

Stephen J. Demczak