Canyon Fuel Company, LLC
A Subsidiary of Bowie Resource Partners, LLC

Sufco Mine
597 South SR24
Salina, Utah 84654
(435) 286-4880
Fax (435) 286-4499

March 30, 2020

Utah Coal Program
Utah Division of Oil, Gas, and Mining
1594 West North Temple, Suite 1210
P. O. Box 145801
Salt Lake City, Utah 84114-5801

Dear Program Supervisor:

Enclosed are Quarterly inspection reports for Canyon Fuel Company's SUFCO Mine: Minesite Primary Sedimentation Pond, Minesite Sedimentation Overflow Pond, Waste Rock Disposal Site and the associated Waste Rock North and South Sedimentation Pond.

These certifications are being submitted prior to SUFCO's Annual Report as required by R645-514.

Sincerely,
CANYON FUEL COMPANY, LLC
SUFCO Mine

Jacob D. Smith, P.E.
Technical Services Manager

JDS:jn

cc: DOGM Sediment Pond Inspection File
Amanda Richard

SUFPUB\GOVT2020\DOGM\SEDIMENTPOND&WASTEROCKINSPECTIONS\QTRCERT20.LTR.doc

CANYON FUEL COMPANY - SUFCO MINE

Coal Refuse Pile Quarterly Inspection Report

Inspector Amanda Lewis Title Env. Engineer
Date 03/5/20 Permit # ACT/041/002

1. Foundation Preparation (vegetation, topsoil removal?) __ Yes X No

2. Lift Thickness (inches) 12 (+ or - 1 Ft compacted)

3. Compaction X Yes __ No

4. Burning (specify extent and location) __ Yes X No

None Observed

5. Angle of Slope 2:1

6. Seepage (specify location, color, & appr. volume) __ Yes X No

None Observed

7. Cracks or Scarps (location and size) __ Yes X No

None Observed

8. Major Erosion Problems (location and extent) __ Yes X No

None Observed

9. Water Impounding Against Toe __ Yes X No

None Observed

10. Any appearance of instability, structural weakness or other hazardous conditions __ Yes X No

None Observed

PROFESSIONAL ENGINEER
3/30/20
No. 9073281
JACOB D. SMITH
STATE OF UTAH

Jacob D. Smith, P.E.
Registration No. 9073281
State of Utah

CANYON FUEL COMPANY - SUFCO MINE

Rock Waste North Sediment Pond Quarterly Inspection Report

Inspector Amanda Lewis Date 03/5/20

1. Dam Structural Weakness

A. Cracks or scarps on crest ___ Yes X No

Nothing Observed

B. Cracks or scarps on slope ___ Yes X No

Nothing Observed

C. Sloughing or bulging on slope ___ Yes X No

Nothing Observed

2. Major Erosion Problems ___ Yes X No

Nothing Observed

3. Surface Movements of Surrounding Slopes ___ Yes X No

Nothing Observed

4. Visible Sumps or Sinkholes in Slurry Surface ___ Yes X No

Nothing Observed

5. Clogging

A. Spillway channels and pipes ___ Yes X No

Channels and pipes clear

B. Decant System ___ Yes X No

Valve is locked

C. Diversion ditches ___ Yes _X_ No

Clear of Debris

6. Seepage (Specify Location, Color and Approx. Volume)

___ Yes _X_ No

Nothing Observed

7. Any appearance of instability, structural weakness, or other hazardous conditions ___ Yes _X_ No

Nothing Observed

8. Other Comments

There is snow in the pond and around the surrounding area.

CANYON FUEL COMPANY - SUFCO MINE

Rock Waste South Sediment Pond Quarterly Inspection Report

Inspector Amanda Lewis Date 03/5/20

1. Dam Structural Weakness

A. Cracks or scarps on crest ___ Yes _X_ No

Nothing Observed

B. Cracks or scarps on slope ___ Yes _X_ No

Nothing Observed

C. Sloughing or bulging on slope ___ Yes _X_ No

Nothing Observed

2. Major Erosion Problems ___ Yes _X_ No

Nothing Observed

3. Surface Movements of Surrounding Slopes ___ Yes _X_ No

Nothing Observed

4. Visible Sumps or Sinkholes in Slurry Surface ___ Yes _X_ No

Nothing Observed

5. Clogging

A. Spillway channels and pipes ___ Yes _X_ No

Channels and pipes clear

B. Decant System ___ Yes _X_ No

Valve is locked

C. Diversion ditches ___ Yes _X_ No

Clear of Debris

6. Seepage (Specify Location, Color and Approx. Volume)

___ Yes _X_ No

Nothing Observed

7. Any appearance of instability, structural weakness, or other hazardous conditions ___ Yes _X_ No

Nothing Observed

8. Other Comments

The pond is snow covered. Nothing is leaving the site and the pond is functioning properly.

09/09/10 MLD

CANYON FUEL COMPANY - SUFCO MINE

Minesite Primary Sediment Pond Quarterly Inspection Report

Inspector Amanda Lewis Date 03/5/20

1. Dam Structural Weakness

A. Cracks or scarps on crest ___ Yes _X_ No

Nothing Observed

B. Cracks or scarps on slope ___ Yes _X_ No

Nothing Observed

C. Sloughing or bulging on slope ___ Yes _X_ No

Nothing Observed

2. Major Erosion Problems ___ Yes _X_ No

Nothing Observed

3. Surface Movements of Surrounding Slopes ___ Yes _X_ No

Nothing Observed

4. Visible Sumps or Sinkholes in Slurry Surface ___ Yes _X_ No

Nothing Observed

5. Clogging

A. Spillway channels and pipes ___ Yes _X_ No

No debris blocking spillway channels and pipes

B. Decant System ___ Yes _X_ No

Valve is locked

C. Diversion ditches ___ Yes _X_ No

Clear of Debris

6. Seepage (Specify Location, Color and Approx. Volume)

___ Yes _X_ No

Nothing Observed

7. Any appearance of instability, structural weakness, or other hazardous conditions ___ Yes _X_ No

Nothing Observed

8. Weir level _X_ Yes ___ No

9. Other Comments

Everything seems to be operating normal.

CANYON FUEL COMPANY - SUFCO MINE

Minesite Sediment Overflow Pond Quarterly Inspection Report

Inspector Amanda Lewis Date 03/5/20

1. Dam Structural Weakness

A. Cracks or scarps on crest ___ Yes X No

Nothing Observed

B. Cracks or scarps on slope ___ Yes X No

Nothing Observed

C. Sloughing or bulging on slope ___ Yes X No

Nothing Observed

2. Major Erosion Problems ___ Yes X No

Nothing Observed

3. Surface Movements of Surrounding Slopes ___ Yes X No

Nothing Observed

4. Visible Sumps or Sinkholes in Slurry Surface ___ Yes X No

Nothing Observed

5. Clogging

A. Spillway channels and pipes ___ Yes X No

No debris blocking spillway channels and pipes.

B. Decant System ___ Yes X No

Valve is locked

C. Diversion ditches ___ Yes _X_ No

Clear of Debris

6. Seepage (Specify Location, Color and Approx. Volume)

___ Yes _X_ No

Nothing Observed

7. Any appearance of instability, structural weakness, or other hazardous conditions ___ Yes _X_ No

Nothing Observed

8. Weir level _X_ Yes ___ No

9. Other Comments

Everything seems to be operating normal.