0010

Document Information Form

Mine Number: C/043/001

File Name: Incoming

To: DOGM

From:

Person JACK HIGGINS, PRES.

Company SUMMIT MINERALS INC.

Date Sent: FEB. 3, 1986

Explanation:

MINE SITE EVALUATION INSPECTION REPORT

cc:

File in:
C/043/001, 1986, **Incoming**
Refer to:
- ❑ **Confidential**
- ❑ **Shelf**
- ❑ **Expandable**

Date _____ For additional information

0010

RECEIVED

FEB - 3 1986

DIVISION OF OIL GAS & MINING

Orig mine file
cc J. Helfrich
K. May
L. Overton

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a	1b	1c
Y Y M M	Batch	Report

2. Name of Permittee: Jack Higgins, Pres. Summit Minerals Inc

3. Street Address: 2783 Holiday Ranch

4. City: Park City

5. State: UT

6. Zip Code: 84060

7. Area Code:

8. Telephone Number: -

9. MSHA Number: - -

10. Date of Inspection (Y Y M M D D): 861219

11. State Permit Number: INA 043 001

12. Name of Mine: BLACKHAWK #1

13. County Code: 043

14. State Code: UT

15. Strata:

16. State Area Office: 01

17. OSM Field Office No.: 02

18. OSM Area Office No.:

19. OSM Sample No.:

20. Type of Inspection (Code): C

21. Joint Inspection Yes: X No:

22. Inspector's ID No.: 116

23. Status

A		Type of Permit
B	I	Mine Status (Code)
C	20	Type of Facility (Code)
D	.	Number of Permitted Acres
E	00015.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A		Steep Slope	E		Anthracite
B		Mountain Top Removal	F		Federal Lands
C		Prime Farmlands	G		Indian Lands
D		Alluvial Valley Floors	H		Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	2	Distance Prohibitions
B	3	Mining Within Permit Boundaries
C	2	Signs and Markers
D	2	Sediment Control Measures
E	2	Design and Certification Requirements—Sediment Control
F	1	Effluent Limits
G	2	Surface Water Monitoring
H	2	Ground Water Monitoring
I	3	Blasting Procedures
J	2	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L		Other: Specify _____

Standards That Assure Reclamation Quality and Timeliness

M	3	Topsoil Handling
N	3	Backfilling and Grading
O	3	Following Reclamation Schedule
P	3	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	3	Handling of Acid or Toxic Materials
S	2	
T	3	
U	3	
V		
W		

File in:
- ☐ Confidential
- ☐ Shelf
- ☐ Expandable

Refer to Record No 0010 Date 2-3-86
In C/043/001, 1986, Incoming
For additional information

Distribution: Original - Field Office, Green - Headquarters, Blue - State's Copy, Yellow - Inspector's Copy, Pink - File Copy

IE - 163 (1/83)

0010

RECEIVED

FEB - 3 1986

DIVISION OF OIL GAS & MINING

bring mine file
cc J. Helfrich
K. Gray
L. Braxton

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a	1b	1c
Y Y M M	Batch	Report

2. Name of Permittee: JACK Higgins, Pres. Summit Minerals Inc

3. Street Address: 2783 Holiday Ranch

4. City: Park City

5. State: UT

6. Zip Code: 84060

7. Area Code:

8. Telephone Number:

9. MSHA Number:

10. Date of Inspection (Y Y M M D D): 861219

11. State Permit Number: IMA 043 001

12. Name of Mine: BLACKHAWK #1

13. County Code: 043

14. State Code: UT

15. Strata:

16. State Area Office: 01

17. OSM Field Office No.: 02

18. OSM Area Office No.:

19. OSM Sample No.:

20. Type of Inspection (Code): C

21. Joint Inspection Yes: X No:

22. Inspector's ID No.: 116

23. Status

A		Type of Permit
B	I	Mine Status (Code)
C	20	Type of Facility (Code)
D		Number of Permitted Acres
E	00015.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A		Steep Slope	E		Anthracite
B		Mountain Top Removal	F		Federal Lands
C		Prime Farmlands	G		Indian Lands
D		Alluvial Valley Floors	H		Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	2	Distance Prohibitions
B	3	Mining Within Permit Boundaries
C	2	Signs and Markers
D	2	Sediment Control Measures
E	2	Design and Certification Requirements—Sediment Control
F	1	Effluent Limits
G	2	Surface Water Monitoring
H	2	Ground Water Monitoring
I	3	Blasting Procedures
J	2	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L		Other: Specify

Standards That Assure Reclamation Quality and Timeliness

M	3	Topsoil Handling
N	3	Backfilling and Grading
O	3	Following Reclamation Schedule
P	3	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	3	Handling of Acid or Toxic Materials
S	2	Highwall Elimination
T	3	Downslope Spoil Disposal
U	3	Post Mining Land Use
V		Cessation of Operations: Temporary
W		Other

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

26. State Permit Number IWA 043 001

27. Date of Inspection (Y Y M M D D) 86/12/19

28. Yes ☐ No ☐ Do mining and reclamation activities on the site comply with the plans in the permit? If no, provide narrative to support this determination.

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a. 04 Number of Completes 29b. 02 Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a. 02 Number of Completes 30b. 06 Number of Partials

31. Has inspection frequency been met?

31a. Yes ☒ No ☐ Completes 31b. Yes ☐ No ☒ Partials

32. FEDERAL ENFORCEMENT INFORMATION. [Enter violation number. Check appropriate box(es)]

	Ten-Day Notice No.	Notice of Violation No.	Cessation Order No.	Violation Codes
A	☐	☐	☐	Authorizations to Operate
B	☐	☐	☐	Signs and Markers
C	☐	☐	☐	Backfilling and Grading
D	☐	☐	☐	Highwall Elimination
E	☐	☐	☐	Rills and Gullies
F	☐	☐	☐	Improper Fills
G	☐	☐	☐	Topsoil Handling
H	☐	☐	☐	Sediment Ponds
I	☐	☐	☐	Effluent Limits
J	☐	☐	☐	Water Monitoring
K	☐	☐	☐	Buffer Zones
L	☐	☐	☐	Roads
M	☐	☐	☐	Dams
N	☐	☐	☐	Blasting
O	☐	☐	☐	Revegetation
P	☐	☐	☐	Spoil on the Downslope
Q	☐	☐	☐	Mining Without Permit
R	☐	☐	☐	Exceeding Permit Limits
S	☐	☐	☐	Distance Prohibitions
T	☐	☐	☐	Toxic Materials
U	☐	☐	☐	Other Violations

33. Name of Authorized Representative *(print or type)* HENRY P. HUSTIN

Signature of Authorized Representative Henry P. Austin — Date 1-20-86

Signature of Reviewing Official [illegible] — Date 1/29/86

0 0 0
0 3 0
0 2 0
0 2 0

2783 Holiday Ranch Loop Rd.
Park City, UT 84060

Inspector Henry P. Austin

Others Donna Griffin, OSM; Joe Helfrich, DOGM

Mine Blackhawk Mine

Permit # INA/043/001

Date: 12-19-85

Inspection Type Complete, joint (DOGM)

Conducted on site inspection accompanied by above. No minesite personnel were present, however, maintenance building was unlocked and pick-up truck was parked on site. Snow had been cleared from haulroad/entrance road and there was approx. one foot of snow throughout the permit area. Insized sed. pond was frozen/snow covered, however, it appeared to contain very little water. Diversion berms around the pad/working area and along haulroad appeared contiguous, however, were snow covered. Portal area was completely drifted over with snow cover.

This site has not produced coal for years and has gone through a series of operators/permittees. Refer to Utah/DOGM Board Order (Docket #'s 85-055,07 Cause #'s INA/043/001, for chronology of past/present owners and enforcement actions taken against Summit Minerals, Inc. and it's president Jack Higgins. (Enclosed Copy of Board Order) Also refer to Utah/DOGM letter of 12-13-85 to Summit Minerals, Inc. and Jack Higgins concerning portal closure requirements. (Enclosed copy of letter) These requirements were discussed with Lamar Bishop, MSHA, at their Price, UT office on 12-18-85.

Telephone correspondence on 1-21-86 indicates there has been no further activity on site, and none of the provisions within the Board Order have been satisfied by Summit Minerals, Inc.

(cont.)

According to JOE HEIRRH, UTAH/DOGM, a civil complaint was filed on 1-20-86 at the Summit County courthouse by UTAH/DOGM against Summit Minerals, Inc. and it's president Jack Higgins.

The Board Order and Cessation Order 85-6-2-1, CO 85-1-2-1 and CO 85-1-1-1 have prevented any further development or work on site since 11-5-85.

However, CO 85-1-2-1 was issued on 8-14-85 for failure to abate the previously issued CO 85-1-1-1, which is a questionable procedure, which has also been discussed with UTAH/DOGM.

Alternative enforcement actions including UTAH/DOGM Board Hearings/Orders, and civil restraining actions through the Summit County courthouse should have been initiated earlier and restrained access to the site after UTAH/DOGM on site inspections of 4-12-85 (complete) and 5-8-85 indicated further site development. UTAH/DOGM CO 85-1-1-1 required immediate cessation of all activities and submittal of a mining and reclamation plan, OR reclamation of the site within Permanent Program Guidelines within 60 days (4-30-85). The permittee/operator did not comply with the requirements of CO 85-1-1-1, and therefore, the alternative enforcement actions should have been initiated after the 4-30-85 abatement deadline.

Performance standards indicated as not applicable do not exist on site.

HPA