0023

Document Information Form

Mine Number: C/043/001

File Name: Incoming

To: DOGM

From:

Person N/A

Company SUMMIT MINERALS INC.

Date Sent: MAR 9, 1987

Explanation:

MINE SITE EVALUATION INSPECTION Report

cc:

File in:
C/043/001, 1987, **Incoming**
Refer to:
- ❑ **Confidential**
- ❑ **Shelf**
- ❑ **Expandable**

Date _____ For additional information

0023

Utah DOGM

File PRO/043/001 #5
copy to Dave Lot

RECEIVED
MAR 09 1987
DIVISION OF
OIL, GAS & MINING

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a	1b	1c
Y Y M M	Batch	Report

2. Name of Permittee	Summit minerals Inc
3. Street Address	221 West 2100 south
4. City	Salt Lake City
5. State	
6. Zip Code	84115
7. Area Code	801
8. Telephone Number	486-1861
9. MSHA Number	42-01284-
10. Date of Inspection (Y Y M M D D)	870224
11. State Permit Number	INA 043 001
12. Name of Mine	Summit minerals #1
13. County Code	043
14. State Code	UT
15. Strata	
16. State Area Office	01
17. OSM Field Office No.	02
18. OSM Area Office No.	
19. OSM Sample No.	
20. Type of Inspection (Code)	C
21. Joint Inspection Yes	X
21. Joint Inspection No	
22. Inspector's ID No.	116

23. Status

A	01	Type of Permit
B	I	Mine Status (Code)
C	20	Type of Facility (Code)
D		Number of Permitted Acres
E	00015.0	Number of Disturbed Acres

**perm. program reclamation permit under review.

24. Type of Activity (check applicable boxes).

A		Steep Slope	E		Anthracite
B		Mountain Top Removal	F		Federal Lands
C		Prime Farmlands	G		Indian Lands
D	X	Alluvial Valley Floors	H		Other

-potential AVF disturbance-

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	2	Distance Prohibitions
B	3	Mining Within Permit Boundaries
C	1	Signs and Markers
D	2	Sediment Control Measures
E	2	Design and Certification Requirements—Sediment Control
F	1	Effluent Limits
G	3	Surface Water Monitoring
H	3	Ground Water Monitoring
I	3	Blasting Procedures
J	2	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L		Other: Specify

Standards That Assure Reclamation Quality and Timeliness

M	3	Topsoil Handling
N	3	Backfilling and Grading
O	3	Following Reclamation Schedule
P	3	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	3	Handling of Acid or Toxic Materials
S		
T		
U		
V		
W		

File in:
- ☐ Confidential
- ☐ Shelf
- ☐ Expandable

Refer to Record No 0023 **Date** 3-9-87
In C/043/001, F87, **Incoming**
For additional information

0023

Utah DOGM

File PRO/043/001 #5
copy to Dave Lot

RECEIVED
MAR 09 1987
DIVISION OF
OIL, GAS & MINING

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a	1b	1c
Y Y M M	Batch	Report

2. Name of Permittee: Summit Minerals Inc

3. Street Address: 221 West 2100 South

4. City: Salt Lake City

5. State:

6. Zip Code: 84115

7. Area Code: 801

8. Telephone Number: 486-1861

9. MSHA Number: 42-01284-

10. Date of Inspection (Y Y M M D D): 870224

11. State Permit Number: INA 043 001

12. Name of Mine: Summit Minerals #1

13. County Code: 043

14. State Code: UT

15. Strata:

16. State Area Office: 01

17. OSM Field Office No.: 02

18. OSM Area Office No.:

19. OSM Sample No.:

20. Type of Inspection (Code): C

21. Joint Inspection Yes: X No:

22. Inspector's ID No.: 116

23. Status

** perm. program reclamation permit under review.

A	01	Type of Permit
B	I	Mine Status (Code)
C	20	Type of Facility (Code)
D		Number of Permitted Acres
E	00015.0	Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

A		Steep Slope	E		Anthracite
B		Mountain Top Removal	F		Federal Lands
C		Prime Farmlands	G		Indian Lands
D	X	Alluvial Valley Floors	H		Other

-potential AVF disturbance-

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

A	2	Distance Prohibitions
B	3	Mining Within Permit Boundaries
C	1	Signs and Markers
D	2	Sediment Control Measures
E	2	Design and Certification Requirements--Sediment Control
F	1	Effluent Limits
G	3	Surface Water Monitoring
H	3	Ground Water Monitoring
I	3	Blasting Procedures
J	2	Haul/Access Road Design and Maintenance
K	3	Refuse Impoundments
L		Other: Specify

Standards That Assure Reclamation Quality and Timeliness

M	3	Topsoil Handling
N	3	Backfilling and Grading
O	3	Following Reclamation Schedule
P	3	Revegetation Requirements
Q	3	Disposal of Excess Spoil
R	3	Handling of Acid or Toxic Materials
S	3	Highwall Elimination
T	3	Downslope Spoil Disposal
U	3	Post Mining Land Use
V		Cessation of Operations: Temporary
W		Other

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

26. State Permit Number IWA 043 001

27. Date of Inspection (Y Y M M D D) 870224

28. Yes ☐ No ☐ Do mining and reclamation activities on the site comply with the plans in the permit? If no, provide narrative to support this determination.

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a. 01 Number of Completes 29b. 01 Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a. 02 Number of Completes 1/4 completes required for inactive sites. 30b. 00 Number of Partials

31. Has inspection frequency been met?

31a. Yes ☐ No ☒ Completes

The mandate to do completes was given by OSM on Jan, 1987. There are no approved plans for what to do complete inspections

b. Yes ☒ No ☐ Partials

32. FEDERAL ENFORCEMENT [Check appropriate box(es)]

	Ten-Day Notice No.		Cessation Order No.		Violation Codes
A	☐		☐		Authorizations to Operate
B	☐		☐		Signs and Markers
C	☐	☐	☐		Backfilling and Grading
D	☐	☐	☐		Highwall Elimination
E	☐	☐	☐		Rills and Gullies
F	☐	☐	☐		Improper Fills
G	☐	☐	☐		Topsoil Handling
H	☐	☐	☐		Sediment Ponds
I	☐	☐	☐		Effluent Limits
J	☐	☐	☐		Water Monitoring
K	☐	☐	☐		Buffer Zones
L	☐	☐	☐		Roads
M	☐	☐	☐		Dams
N	☐	☐	☐		Blasting
O	☐	☐	☐		Revegetation
P	☐	☐	☐		Spoil on the Downslope
Q	☐	☐	☐		Mining Without Permit
R	☐	☐	☐		Exceeding Permit Limits
S	☐	☐	☐		Distance Prohibitions
T	☐	☐	☐		Toxic Materials
U	☐	☐	☐		Other Violations

33. Name of Authorized Representative *(print or type)* HENRY T. HUSTIAN

Signature of Authorized Representative Henry T. Hustian — Date 3/3/87

Signature of Reviewing Official — Date 3-5-87

00 0
03 0
02 0
01 5

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

26. State Permit Number IN A 043 001

27. Date of Inspection (Y Y M M D D) 870224

28. Yes ☐ No ☐ Do mining and reclamation activities on the site comply with the plans in the permit? If no, provide narrative to support this determination.

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a. 01 Number of Completes 29b. 01 Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a. 02 Number of Completes 1/4 completes required for inactive sites. 30b. 00 Number of Partials

31. Has inspection frequency been met?

31a. Yes ☐ No ☒ Completes 31b. Yes ☒ No ☐ Partials

32. FEDERAL ENFORCEMENT INFORMATION. [Enter violation number. Check appropriate box(es)]

	Ten-Day Notice No.	Notice of Violation No.	Cessation Order No.	Violation Codes
A	☐	☐	☐	Authorizations to Operate
B	☐	☐	☐	Signs and Markers
C	☐	☐	☐	Backfilling and Grading
D	☐	☐	☐	Highwall Elimination
E	☐	☐	☐	Rills and Gullies
F	☐	☐	☐	Improper Fills
G	☐	☐	☐	Topsoil Handling
H	☐	☐	☐	Sediment Ponds
I	☐	☐	☐	Effluent Limits
J	☐	☐	☐	Water Monitoring
K	☐	☐	☐	Buffer Zones
L	☐	☐	☐	Roads
M	☐	☐	☐	Dams
N	☐	☐	☐	Blasting
O	☐	☐	☐	Revegetation
P	☐	☐	☐	Spoil on the Downslope
Q	☐	☐	☐	Mining Without Permit
R	☐	☐	☐	Exceeding Permit Limits
S	☐	☐	☐	Distance Prohibitions
T	☐	☐	☐	Toxic Materials
U	☐	☐	☐	Other Violations

33. Name of Authorized Representative *(print or type)* HENRY P. HUSTON

Signature of Authorized Representative Henry P. Huston — Date 3/3/87

Signature of Reviewing Official [illegible] — Date 3-5-87

000
030
020
015

Company Summit Minerals, Inc. Mine Summit Minerals

221 West 2100 South

Salt Lake City, UT 84115

Permit # INA 043 001

Date: 2-24-87

RECEIVED MAR 09 1987 DIVISION OF OIL GAS & MINING

Inspector HENRY P. AUSTIN

Inspection Type Complete, Routine, joint

Others DAVE LOF, SUE LINNER - DOGM

DALE WRIGHT - Summit

Conducted complete inspection on site accompanying DAVE LOF of DOGM, identified myself to DALE WRIGHT - Summit employee who was on site today.

The appropriate mine entrance sign is in place, however, there has been only minor maintainance activities on site since my first inspection here 12-19-85. There WAS several inches of snow throughout the disturbed area - no surface runoff occuring during the inspection. The DOGM has made an apparent completeness finding for a reclamation plan submittal - the DOGM finding is dated 1-23-87. The DOGM has also accepted a real property collateral bond for the proposed permit area of 14.4 acres.

The operators are currently gathering environmental data necessary to submit a mining plan also for this site. According to Mr. Wright, the Utah Div. of Water Resources were to be on site today to evaluate potential impacts to Chalk Creek from a proposed new crossing - a spanned culvert to replace the current wooden structure. Coordination of this field review thru the various Utah agencies involved was suggested to Ms. Linner, to enable the respective staff members to share views on site.

According to Ms. Barbara Roberts, DOGM Attorney, via telephone on 3-3-87, the BOARD (DOGM) action filed in Coalville, UT to collect unpaid civil penalties from Mr. Jack Higgins, is currently on appeal, and the penalties are unpaid.

Subjects discussed on site included proposed location of sediment pond in old gravel quarry area on east portion of permit, potential affect on AVF in this area, new portal location and permanent sealing of old portal. According to available info., only backfilling was accomplished to temporarily seal the portal.

Spoke to Tony Gabassi at MSHA/Price office who indicated via telephone on 3-3-87 that his office has had no contact with Summit Minerals, to his knowledge. DOGM letter dated 12-13-86 to Jack Higgins, President of Summit Minerals, Inc., required the operator to notify MSHA "within one working day of receipt of letter" concerning plans to seal the portal. This letter was not copied to the MSHA office - and I discussed this letter with MSHA representatives Tony Gabassi and Lamar Bishop the week of 12-19-85 to make them aware of conditions and DOGM action on the site.

Performance standards indicated as not applicable either do not exist on site or are not required yet as no permit has been approved here.

— HPA —

Performance standards indicated as out-of-compliance have been addressed by DOGM Cessation Orders C.85-1-2-1 (issued 8-14-85) and C.85-6-2-1 (issued 11-4-85)

— HPA —