7130 0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gd SCL

inspection report

Permit No. INA/043/001
Inspection Date December 8, 1989

Permittee/Operator Name Summit Minerals, Inc.
Business Address 221 West 2100 South
City Salt Lake City State Utah Zip 84115
Mine Summit Minerals #1 ☐ Surface ☒ Underground ☐ Other
County Summit State Utah
Company Official(s) None
State Official(s) Harold G. Sandbeck
Time of inspection 11:00 ☒ a.m. ☐ p.m. to 12:15 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection September 7, 1989 Weather conditions Clear and Cold
Acreage 0 ☒ Permitted 16 ☒ Disturbed ☐ Regraded ☐ Seeded 16 ☒ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☒	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☒	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☐	☐	☒	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☐	☒	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/043/001

Inspection Date December 8, 1989

Please number comments to correspond with topics on previous page.

General Comments: The operator was not available to accompany the undersigned inspector on this complete inspection. No evidence of mining or mining related activities were noted.

1.) Permit:

Summit Minerals has been denied a permit. Forfeiture of the reclamation bond is currently ongoing and the reader is referred to the Division correspondence files for additional information.

Copy of report mailed to Jack Higgins (Summit Minerals), Pace Office and Brian Smith (OSM)

Copy of report given to Sue Linner and Joe Helfrich - DOGM

Inspector's signature Harold G. Sandford No. 27

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE