0004

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: September 11, 1991
1:30 P. M. - 2:30 P. M.

Permittee and/or Operator's Name: Summit Minerals, Inc.
Business Address: 221 W. 2100 S., Salt Lake City, UT 84115
Phone: (801) 486-1861
Mine Name: Summit #1 Permit Number: INA/043/001
Type of Mining Activity: Underground X Surface ___ Other ___
County: Summit Company Official(s): None Present
State Officials(s): Priscilla Burton
Federal Official(s): None
Partial: ___ Complete X Date of last Inspection: 06/11/91
Weather Conditions: Partly cloudy, 70's.
Acreage: Permitted 0 Disturbed 16 Regraded ___
Seeded ___ Bonded 16 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	(X)	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	(X)	( )
b. DIVERSIONS	(X)	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	(X)	( )
f. EFFLUENT LIMITATIONS	( )	( )	(X)	( )
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	(X)	( )
7. COAL PROCESSING WASTE	( )	( )	(X)	( )
8. NONCOAL WASTE	( )	(X)	( )	(X)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	(X)	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	(X)	( )
12. BACKFILLING AND GRADING	( )	( )	(X)	( )
13. REVEGETATION	( )	( )	(X)	( )
14. SUBSIDENCE CONTROL	( )	( )	(X)	( )
15. CESSATION OF OPERATIONS	(X)	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	(X)	( )
b. DRAINAGE CONTROLS	( )	(X)	( )	(X)
c. SURFACING	( )	( )	(X)	( )
d. MAINTENANCE	( )	( )	(X)	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	(X)	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	(X)	( )	( )	( )

an equal opportunity employer

INSPECTION REPORT

(Continuation sheet) Page 2 of 2

PERMIT NUMBER: INA/043/001 DATE OF INSPECTION: 09/11/91

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENT:

The gate was securely closed. A hammer was required to open the hasp. Having no hammer, I walked the access road to the site. There was no sign of any activity at the site. Except for the bird citings reported in the last complete inspection, conditions were virtually the same.

1. PERMITS
Map S1 1008, Existing Contour, is the map that depicts the surface conditions at the site.

8. NON-COAL WASTE
The sediment impoundment was empty except for piles of empty glass containers. Since this site is presently inactive, it is suggested that the next inspector bring along garbage sacks to carry out some of this debris.

16.b. ROADS Drainage control
Heading south along the access road, after the bridge, the berm on the East side is breached. Cobbles and sand are being carried to the grassy sward below. Apparantly a similar situation occured on the West side and was managed with straw bales. The berm on the East side should be repaired or straw bales should be placed at this location.

Copy of this Report:
Mailed to: Brian Smith(OSM); Jack Higgins (Summit)
Given to: Daron Haddock, DOGM; Joe Helfrich, DOGM

Inspector's Signature & Number: Pamella Burton #37

Date: September 12, 1991