0006

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/043/001
Inspection Date Feb 27, 1991

Permittee/Operator Name Summit Minerals, Inc.
Business Address 221 W. 2100 South, Salt Lake City
City SLC State Utah Zip 84115
Mine Summit Minerals #1 ☐ Surface ☒ Underground ☐ Other
County Summit State Utah
Company Official(s) Did not have Company representation.
State Official(s) Daron R. Haddock
Time of inspection 12:30 ☐ a.m. ☒ p.m. to 1:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection June 6, 1990 Weather conditions Clear Sunny Mild
Acreage 0 ☐ Permitted 16 ☐ Disturbed ☐ Regraded ☐ Seeded 16 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☒	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☒	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☐	☐	☒	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☐	☒	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/043/001

Inspection Date Feb 27, 1991

Please number comments to correspond with topics on previous page.

General Comments: This site has essentially been abandoned by the operator. Summit Minerals was denied a permit. Bond forfeiture proceedings were recently concluded and the Division is in the process of procurring funds to conduct reclamation activities at the site. The Division goal is to complete reclamation grading + revegetation by fall 1991.
There has been some confusion as to whether or not inspections would be required at this site since the permit was denied. The Division has determined that inspections will be done on a regular basis.
Site Conditions: There is no evidence of any recent activity at the site. Most of this site is still covered with snow and no drainage was observed leaving the site.
No hazardous conditions or evidence of imminent harm were apparent.

Copy of report mailed to Jack Higgins (Summit Minerals) Brian Smith (OSM)

Copy of report given to Joe Helfrich DOGM

Inspector's signature Daron R. Haddock No. 28

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE