0012

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Partial: x Complete:___ Exploration:___
Inspection Date & Time: 2/25/93, 10:00 to 10:15
Date of Last Inspection: 1/29/93

Mine Name: Summit #1 County: Summit Permit Number: INA/043/001
Permittee and/or Operator's Name: Summit Minerals Inc.
Business Address: 221 West 2100 South, SLC UT 84115
Type of Mining Activity: Underground x Surface___ Prep. Plant___ Other___
State Officials(s): Priscilla Burton
Company Official(s): none present
Federal Official(s): none present
Weather Conditions: sunshine, cool
Existing Acreage: Permitted- 0 Disturbed-16 Regraded- 0 Seeded- 0 Bonded- 16
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: __Exploration/__Active/ x Inactive/__Temporary Cessation/ x Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[x]	[ ]	[ ]
2. SIGNS AND MARKERS	[x]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[ ]	[ ]	[ ]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[x]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[x]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[x]	[ ]	[x]	[ ]

INSPECTION REPORT

(Continuation sheet) Page 2 of 2

PERMIT NUMBER: INA/043/001 DATE OF INSPECTION: 2/25/93

(Comments are Numbered to Correspond with Topics Listed Above)

There has been no entry to the site. The site is snow covered and inaccessible. There was no evidence of slides.

21. BONDING & INSURANCE

A draft letter has been routed up to Division management and is under review. The letter is to adjacent landowners inquiring after their interest in purchasing the Division's parcel located in Section 24 T5S R4E (near Wallsburg, UT). This parcel was placed as a real property collateral bond by Johnell Limited Partnership for the Summit #1 mine on June 4, 1986. Bond was calculated at $120,300.00. The property ownership was transferred at trustee's sale (9/11/90) to the Division. The appraised value at the time of sale was $15,000.00. The amount of the bond less the value of the property is a sum of $105,300.00 which is still owing by Summit Minerals Inc.

The adjacent landowners are listed below.

1. Miriam F. Davis; 65 East Kensington Ave, SLC UT 84115
2. Johnell Limited Partnership; 338 Hanson Avenue, SLc UT 84115
3. Alan Knudsen; P.O. Box 2228, Sandy UT 84091-2228
4. Narobe Inc.; 65 East Kensington Ave, SLC UT 84115
5. Valley Rnaches Inc.; P.O. Box 477, Delta UT 84626

Copy of this Report:

Mailed to: Marcia Petta (OSM), Keith Bates (Keith H. Bates Investment Co.)

Given to: Joe Helfrich (DOGM), Daron Haddock (DOGM)

Inspector's Signature: Priscilla Bonifon # 37 Date: 2/25/93