4-14-89
7022

0020

SCL

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: March 16, 1989
8:00 a.m. to 11:30 a.m.

Permittee and/or Operators Name: Summit Coal Company
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: INA/043/008
Type of Mining Activity: Underground XXX Surface ____ Other ____
County: Summit
Company Official (s): None
State Official(s): Harold G. Sandbeck and Joe Helfrich
Partial: ____ Complete: XXX Date of Last Inspection: February 16, 1989
Weather Conditions: Clear and cool
Acreage: Permitted 170 Disturbed 5.5 Regraded ____ Seeded ____ Bonded 5.5
Enforcement Action: C89-27-1-1 and C89-27-2-1 (SEE #1)

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	(XX)	( )	(XX)
2. SIGNS AND MARKERS	(XX)	( )	( )	( )
3. TOPSOIL	(XX)	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	( )	( )	( )
b. DIVERSIONS	( )	(XX)	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	(XX)	( )	( )	( )
f. EFFLUENT LIMITATIONS	(XX)	( )	( )	( )
5. EXPLOSIVES	( )	( )	(XX)	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	(XX)	( )	( )
7. COAL PROCESSING WASTE	( )	( )	(XX)	( )
8. NONCOAL WASTE	(XX)	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX)	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	(XX)	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	(XX)	( )	( )	( )
12. BACKFILLING AND GRADING	(XX)	( )	( )	( )
13. REVEGETATION	( )	(XX)	( )	( )
14. SUBSIDENCE CONTROL	(XX)	( )	( )	( )
15. CESSATION OF OPERATIONS	(XX)	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	(XX)	( )	( )	( )
b. DRAINAGE CONTROLS	(XX)	( )	( )	( )
c. SURFACING	(XX)	( )	( )	( )
d. MAINTENANCE	(XX)	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	(XX)	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	( )	( )	(XX)	( )

an equal opportunity employer

PERMIT NUMBER: INA/043/008 DATE OF INSPECTION March 16, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. A complete inspection was conducted without company representation. On October 13, 1988, the mine ceased operations. During the field inspection, no mine related activity was noted. Ground conditions were wet.

1. Permits.

C89-27-1-1 was issued on March 2, 1989 (Mailed from office) for failure to abate N88-27-7-4, 1 of 4. N88-27-7-4, 1 of 4 had been issued on December 2, 1988 for failure to certify the Class I haul road and the sediment pond.

C89-27-2-1 was issued on March 16, 1989 (Mailed from office) for failure to abate N88-27-8-1. N88-27-8-1 had been issued on December 16, 1988 for failure to respond to the Division's Conditional approval letter dated September 30, 1988.

Liability Insurance. On March 20, 1989, the undersigned inspector called the operator's insurance company, Evergreen Insurance Associated, Incorporated, and determined that the operator's insurance has lapsed, but it is still in effect.

15. Cessation Of Operations.

The two entrance gates were up and in the closed position. Signs were in place to warn the public to keep out.

The operator installed a fence across the main access mine portal in conjunction with signs warning the public to keep out.

The operator was advised to restrict access to the fan and beltline portals.

Copy of this Report:
Mailed to: Jack Blonquist (Manager), Price Office and Brian Smith (OSM)
Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: Harvey G. Tanner #27 Date: 3/31/89