0006

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/043/008
Inspection Date August 27, 1991

Permittee/Operator Name Summit Coal Company
Business Address P.O. Box 646
City Coalville State Utah Zip 84017
Mine Boyer ☐ Surface ☒ Underground ☐ Other
County Summit State Utah
Company Official(s) None
State Official(s) Daron Haddock
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 2:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection July 6, 1991 Weather conditions Overcast, threatening rain
Acreage 170 ☐ Permitted 5.5 ☐ Disturbed ☐ Regraded ☐ Seeded 5.5 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☒
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ~~ANA~~/043/008

Inspection Date August 27, 1991

Please number comments to correspond with topics on previous page.

3. Topsoil: The topsoil stockpile was inspected. A sign is in place on the pile. A good stand of vegetation appears to be adequately protecting the pile from erosion.
4. Hydrologic balance: Some rilling on the road and pad areas is indicative that a recent storm has hit the area. All disturbed area runoff was diverted to the sediment pond which appears to be in good condition.
12. Backfilling + Grading: A small exploration project has been approved which allowed American Coal Co-op to conduct a reconnaissance inspection of the underground workings. The original approval required that the portals be resealed by August 9, 1991. On August 8th a request for an extension of time to complete the project was recieved at the Division office. An extension was granted and the applicant now has till August 31, 1991 to complete the backfilling.
At this time the reconnaissance has been completed but the ~~por~~ middle + north portals remain open. They are however barracaded by chain link fence to preclude someone from entering the mine. A phone call to Mr. Bob Graham on August 28, 1991 confirmed that the portals would be sealed by the August 31st dead line.

Copy of report mailed to Brian Smith OSM

Copy of report given to Joe Helfrich DOGM

Inspector's signature Daron R. Haddock No. #28

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE