0007

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/043/008
Inspection Date July 6, 1991

Permittee/Operator Name Summit Coal Company
Business Address P.O. Box 646
City Coalville State Utah Zip 84017
Mine Boyer ☐ Surface ☒ Underground ☐ Other
County Summit State Utah
Company Official(s) Bob Graham Kelly Jones with American Coal Co-op Inc,
State Official(s) Daron Haddock
Time of inspection 1:00 ☐ a.m. ☒ p.m. to 5:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection June 11, 1991 Weather conditions Warm, Sunny
Acreage 170 ☐ Permitted 5.5 ☐ Disturbed ☐ Regraded ☐ Seeded 5.5 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☒
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☒
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/043/008

Inspection Date July 6, 1991

Please number comments to correspond with topics on previous page.

4. Hydrologic balance; The site, including the sediment pond is dry. There is no evidence of runoff leaving the site. The diversions, although in need of maintenance, appear to be functioning properly.

12. Backfilling + Grading 15. Cessation of Operations:
On June 20, 1991, the Division recieved an application for a minor coal exploration permit at the Boyer site. Essentially the company involved, American Coal Co-op, wanted to re open the sealed portals and conduct a reconnaissance inspection of the coal seam + roof + floor for possibley reopening the mine. On July 5th the exploration was approved and on the date of the inspection the mine was re-opened. The farthest east portal was used, and three mine personell conducted a short inspection. The company has until August 9th to re seal the portals. All new disturbance at the site is confined to the portal areas and the rest of the site has remained status quo.

Copy of report mailed to Brian Smith OSM

Copy of report given to Joe Helfrich DOGM

Inspector's signature Daron R. Haddock No. #28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE