0009

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/043/008
Inspection Date 5/20/91

Permittee/Operator Name Summit Coal Company
Business Address P.O. Box 646
City Coalville State Utah Zip 84017
Mine Boyer ☐ Surface ☒ Underground ☐ Other
County Summit State Utah
Company Official(s) None
State Official(s) Daron Haddock
Time of inspection 7:30 ☒ a.m. ☐ p.m. to 9:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 4/5/91 Weather conditions Clear, Sunny, Cool
Acreage 170 ☐ Permitted 5.5 ☐ Disturbed ☐ Regraded ☐ Seeded 5.5 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☒
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☒
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☒
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/043/008

Inspection Date 5/20/91

Please number comments to correspond with topics on previous page.

4b. Diversions: The site is essentially dry with no water in any of the diversions. Some maintenance could be done to clean some of the diversions, but at this point they all seem to be working.

4c. Sediment ponds: There is a small amount of water impounded in the sediment pond. The pond has plenty of storage capacity available.

6. Development waste + spoil: The piles of coal refuse material have not changed since the last inspection. No fires were detected.

12. Backfilling: The portals are still sealed with no evidence of any activity around the portal areas.

15. Cessation of operations: The site has changed very little since the last inspection. There's no evidence of any activity at the site.

Copy of report mailed to Brian Smith OSM

Copy of report given to Joe Helfrich DOGM

Inspector's signature Daron R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE