7022 0010 Job NGZ

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/043/008
Inspection Date 4/5/91

Permittee/Operator Name Summit Coal Co.
Business Address P.O. Box 646
City Coalville State Ut Zip 84017
Mine Boyer ☐ Surface ☒ Underground ☐ Other
County Summit State Ut
Company Official(s) ~~Daron Haddock~~ None
State Official(s) Daron Haddock
Time of inspection 6:45 ☒ a.m. ☐ p.m. to 7:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 3/21/91 Weather conditions Sunny Warm
Acreage 170 ☐ Permitted 6.5 ☐ Disturbed ☐ Regraded ☐ Seeded 5.5 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☒
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☒
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/043/008

Inspection Date 4/5/91

Please number comments to correspond with topics on previous page.

4. Hydrologic Balance: The site is completely dry. All snow has melted and there is no running water to be found. The sediment pond is also dry.

6. Spoil disposal: The spoil piles have not changed since the last inspection. No evidence of burning.

General: There appears to have been no activity since the last inspection. The portals remain sealed. No evidence of additional disturbance.

Copy of report mailed to Brian Smith OSM

Copy of report given to Joe Helfrich

Inspector's signature Daron R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE