0012

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340



# inspection report

Permit No. INA/043/008

Inspection Date Feb 27, 1991

Permittee/Operator Name Summit Coal Company

Business Address P.O. Box 646

City Coalville State Utah Zip 84017

Mine Boyer ☐ Surface ☒ Underground ☐ Other

County Summit State Utah

Company Official(s) None

State Official(s) Daron R. Haddock

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 12:15 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection January 26, 1991 Weather conditions clear, sunny + mild

Acreage 170 ☐ Permitted 55 ☐ Disturbed ☐ Regraded ☐ Seeded 55 ☐ Bonded

Enforcement Action none

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☐ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☒ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☐ | ☐ | ☐ | ☐ |
| 4. Hydrologic balance | | | | |
| — Stream channel diversions | ☐ | ☐ | ☐ | ☐ |
| — Diversions | ☒ | ☐ | ☐ | ☒ |
| — Sediment ponds and impoundments | ☒ | ☐ | ☐ | ☒ |
| — Other sediment control measures | ☐ | ☐ | ☐ | ☐ |
| — Surface and groundwater monitoring | ☐ | ☐ | ☐ | ☐ |
| — Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Development waste and spoil disposal | ☒ | ☒ | ☐ | ☒ |
| 7. Coal processing waste | ☐ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☐ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☐ | ☐ | ☐ | ☐ |
| 12. Backfilling and grading | ☒ | ☐ | ☐ | ☒ |
| 13. Revegetation | ☐ | ☐ | ☐ | ☐ |
| 14. Subsidence control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| — Construction | ☐ | ☐ | ☐ | ☐ |
| — Drainage controls | ☐ | ☐ | ☐ | ☐ |
| — Surfacing | ☐ | ☐ | ☐ | ☐ |
| — Maintenance | ☐ | ☐ | ☐ | ☐ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☐ | ☐ | ☐ | ☐ |

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. INA/043/008

Inspection Date Feb 27, 1991

Please number comments to correspond with topics on previous page.

4b: Diversions: Most of the snow on the site has melted. Berms + ditches appear to be functioning properly with disturbed area drainage reporting to the sediment pond.

4c: Sediment Pond: The pond seems to be in good condition. Some water has accumulated but there appears to be adequate storage capacity available. No discharge has occurred

6. Development waste + spoil disposal: The refuse piles were checked for evidence of burning and stability. Problems were not apparent.

12. Backfilling + grading: The portals still remain sealed. There is some settling occurring in the fill at the first portal (approx. 12-14 inches). No evidence of venting was apparent.

General: The site appears to be totally inactive There is no evidence of any recent activity. Six eagles at least 2 of which were bald eagles circled the site during the inspection.

Copy of report mailed to Brian Smith OSM, Richard Blonquist

Copy of report given to Joe Helfrich

Inspector's signature Dave R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE



an equal opportunity employer