0005

Document Information Form

Mine Number: C/043/008

File Name: Outgoing

To: DOGM

From:

Person N/A

Company SUMMIT MINE

Date Sent: N/A

Explanation:

FINDINGS INSPECTION FREQUENCY CHANGE

cc:

File in:
C/043/008, 2003, **Outgoing**
Refer to:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Date _____ For additional information

FINDINGS
INSPECTION FREQUENCY CHANGE
Summit Mine

Summit #1 Mine
Summit Coal Company
C/043/001

The Summit #1 Mine is considered an abandoned site because it meets the criteria of the definition of an abandoned site, "(a) All coal mining and reclamation operations at the site have ceased" and (d)(ii) "The Division forfeited the performance bond and reclaimed the site." The Division of Oil, Gas and Mining proposes that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year as required by R645-301-100. This frequency is in lieu of the inspection frequency of four times per year established in R645-400-130.

There are no impoundments, earthen structures, or other conditions that pose, or may reasonably be expected to change into, imminent dangers to the health or safety of the public or significant environmental harms to lands, air or water resources. Vegetation establishment is preventing erosion. This site is not located near an urbanized area, although the small town of Coalville is about five miles away.

The reclamation bond for this mine was forfeited on June 13, 1989 and the mine was reclaimed as of April 17, 1997. The public notice was published on March 14, 2003 in the Summit County Bee (newspaper in Coalville) and March 12, 2003 in the Park Record (newspaper in Park City). No comments were received.

The site is stable and the stream has been reestablished. The site was inspected on January 28, 2003 and May 6, 2003. There are no outstanding environmental, public health or safety conditions that are present.

Therefore, the inspection frequency will change, effective June 30, 2003.

The Summit Mine is located on:

Fee Land

T3N R6E, SLB&M, Utah

Sec 36: NE1/4 NE1/4, SW1/4 NE1/4 and SE1/4 NE1/4.

O:\043001.SUM\FINAL\Summit.doc

File in:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Refer to Record No 0005 **Date** N/A
In C 043/008, 2003 **Outgoing**
For additional information