DOE Retirement Form
Minerals Program

File Number DOE|019|010

Notification of Operator Required: Yes ___ No ✓
If no, why not? Incline was backfilled and lease dropped.

Mine or Claim Name John Mine

Date Received 2-6-80 Commodity Uranium

Operator (name, address, and phone)

Minerals Recovery Corp.
575 Union Blvd
Lakewood, CO 80228

Legal Description

Township	Range	Section(s)	1/4 1/4 Section
23S	21E	1	NW 1/4

File Comments

MRC rehabilitated a portion of the John Mine in 1980. Surface disturbance was minimal. The incline was backfilled prior to abandonment.

Reviewer's Initials FF

1068R-54